



March 2021 (FOR SKP WEB SUBSCRIBERS)

1\_2021 - **SILCA KEY PROGRAMS PRO v. 31.0.x.xx**

## Silca Key Programs PRO



**Bug fixed**

- Fixed minor bugs
- Fixed bug on Cards 4987-4988-4989-4990-4991-4992



January 2021 (FOR ALL SKP SUBSCRIBERS)

1\_2021 - SILCA KEY PROGRAMS PRO v. 31.0.x.x

## SILCA KEY PROGRAMS PRO

### ■ Management of the new UNOCODE F Series electronic key cutting machines (F900 F800 F600 F400)

The Silca Key Programs PRO manages the new UNOCODE F Series key cutting machines. Below is a list of the SKP PRO functions currently available for the new key cutting machines:

- Machine registry/management
- Key cutting by Silca card numbers
- Key cutting from the work queue
- Key cutting from the Customer Historical
- Key cutting from Master key systems via SSI
- Creation of specific engraving models for the UNOCODE F versions equipped with the Engraving station

**Additional features will be available for all subscribers in the upcoming SKP PRO updates.**

## Silca Key Programs PRO UPGRADE 1/2021



For any info regarding the 1/2021 SKP PRO Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS PRO.





October 2020 (FOR ALL SKP SUBSCRIBERS)

3\_2020 - SILCA KEY PROGRAMS PRO v. 30.4.x.x

## Silca Key Programs PRO UPGRADE 3/2020



For any info regarding the 3/2020 SKP PRO Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS PRO.



**Bug fixed**

- Fixed various issues in the SSI function
- Solved the problem of importing tables with duplicate codes in the “User Series” management”
- Solved the problem of sending a dorsing job to the Micromiller (special function)

September 2020 (FOR SKP PRO WEB SUBSCRIBERS) 2\_2020 - SILCA KEY PROGRAMS PRO v. 30.3.x.x

## Silca Key Programs PRO



**Bug fixed**

- PRIMARY KEY..." Internal error has been fixed
- Fixed bugs on SSI importing DAT file with less cuts than in the card (card 777)
- Partial cuts on user card now works correctly
- Flag "Default machine" now works correctly in SSI.
- Cards P600/Triton have new code tables. To make them work properly, it's necessary to disable a UNOCODE parameter called: "cutting check" in the option menu on-board
- Fixed bug on Copying a Silca card using the CODEMAKER IDEA

July 2020 (FOR ALL SKP SUBSCRIBERS)

2\_2020 - SILCA KEY PROGRAMS PRO v. 30.3.x.x

## Silca Key Programs PRO UPGRADE 2/2020



For any info regarding the 2/2020 SKP PRO Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS PRO.



**Bug fixed**

- Problem solved in updating TRIAX Quattro via USB-PEN
- Problem solved in setting Polish language
- Certain SSI problems solved



March 2020 (FOR SKP PRO WEB SUBSCRIBERS)

1\_2020 - SILCA KEY PROGRAMS PRO v. 30.2.x.x

## Silca Key Programs PRO



**Bug fixed**

- fixed a bug with languages as Japanese, Greek and Russian
- fixed bugs on restoring SKP backup
- fixed bugs with Unicode machines when used with OEM Client Program



January 2020 (FOR ALL SKP SUBSCRIBERS)

1\_2020 - SILCA KEY PROGRAMS PRO v. 30.2.x.x

## Silca Key Programs PRO UPGRADE 1/2020



For any info regarding the 1/2020 SKP PRO Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS PRO.





November 2019 (FOR ALL SKP SUBSCRIBERS)

2\_2019 - SILCA KEY PROGRAMS PRO v. 30.1.x.x

## Silca Key Programs PRO UPGRADE 2/2019




For any info regarding the 2/2019 SKP PRO Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS PRO.






September 2019 (FOR SKP WEB SUBSCRIBERS)

1\_2019 - SILCA KEY PROGRAMS v. 21.11.x.x

| TRIAX-QUATTROCODE |                           |         |           | <b>NEWS</b>   |
|-------------------|---------------------------|---------|-----------|---|
| Lock Manufacturer | Lock-system               | New SSN | Data Card |  |
| MLS               | MLS KT122 ELITE 2 FP 6+5P | 2131    | 2242      | YES   |
| PREFER            | Prefer IAA (5+6+5)        | 2123    | 4682      | NO  |
| VOLVO             | HU152S16 (2T-10W)         | 2125    | 4680      | NO  |
| VOLVO             | HU152S16 (2T-10W)         | 2126    | 4680      | NO  |

| CODE PROGRAM      |  |         |           | <b>NEWS</b>   |
|-------------------|--|---------|-----------|---|
| Lock Manufacturer | Lock-system                            | New SSN | Data Card |  |
| ABUS              | ABUS A93 (5P)                          | 5000    | 4684      | NO  |
| CHERY             |  | 4999    | 4676      | NO  |
| CHICAGO           |  | 5001    | 4685      | NO  |
| MLS               | MLS KT152-MLS 6P FAMILY-RED LINE FP2   | 4992    | 1872      | YES   |
| MLS               | MLS KT052-MLS-6P Antibumping Final FP2 | 4996    | 1872      | YES   |

July 2019 (FOR SKP WEB SUBSCRIBERS)

1\_2019 - SILCA KEY PROGRAMS v. 21.11.x.x

## Silca Key Programs




Bug fixed

- o fixed a bug cutting after decoding the card 869


## TRIAX-QUATTROCODE

**NEWS**

| Lock Manufacturer | Lock-system                | New SSN | Data Card |  |
|-------------------|----------------------------|---------|-----------|---|
| HAFELE            | Hafele HW15R (2t-4W)       | 2113    | 3061      | NO  |
| MLS               | MLS KT122 ELITE 2 FP2 6+5P | 2115    | 2242      | YES   |
| MLS               | MLS KT130 ELITE 1 FP2 6P   | 2117    | 1851      | YES   |
| STANDERS          | Standers (6P)              | 2114    | 1857      | NO  |

## CODE PROGRAM

**NEWS**

| Lock Manufacturer | Lock-system               | New SSN | Data Card |  |
|-------------------|---------------------------|---------|-----------|---|
| GUARD             | Profile G17 T6            | 4994    | 666       | NO  |
| HAFELE            | -                         | 4971    | 4642      | NO  |
| MLS               | MLS KT115 Standard FP2 5P | 4988    | 2273      | YES   |
| MLS               | MLS KT117 Standard FP2 6P | 4989    | 2765      | YES   |
| MLS               | MLS KT119 MLS FP2 6P      | 4991    | 1872      | YES   |
| MLS               | MLS KT138 FAMILY FP2 6P   | 4990    | 1872      | YES   |
| NATIONAL          | NATIONAL                  | 4995    | 1043      | NO  |
| US-LOCK           | -                         | 4993    | 4012      | NO  |



June 2019 (FOR SKP WEB SUBSCRIBERS)

1\_2019 - SILCA KEY PROGRAMS v. 21.11.x.x

## Silca Key Programs UPGRADE 1/2019



For any info regarding the 1/2019 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.



February 2019 (FOR SKP WEB SUBSCRIBERS)

3\_2018 - SILCA KEY PROGRAMS v. 21.10.x.x

## SILCA KEY PROGRAMS




### IMPORTANT NOTICE

Starting from the Silca Key Programs update 1/2019, there will be a change with the minimum required PC characteristics to be able to properly install the SKP:

- Only Windows® 7 operating systems (32 or 64 bit), Windows® 8 (32 or 64 bit) and Windows® 10 (32 or 64 bit) will be supported.
- A minimum of 5 GB of free disk space will be required.
- 4 GB of RAM is recommended.


## TRIAX-QUATTROCODE


**NEWS**

| Lock Manufacturer | Lock-system                 | New SSN | Data Card |  |
|-------------------|-----------------------------|---------|-----------|--|
| MUL.T.LOCK        | Mul-T-Lock Break Secure 3DS | 2024    | 2242      | NO   |
| Wilka             | Carat S3                    | 1983    | 4359      | NO   |
| Wilka             | Carat S5                    | 1984    | 4359      | NO   |
| VAST              | Vast (2T-8W)                | 2095    | 4591      | NO   |
| DOM               | Dom IX7TW (Prf. 282)        | 2054    | 4508      | YES  |
| DOM               | Dom IX7TW (Prf. 283)        | 2055    | 4509      | YES  |
| DOM               | Dom IX7TW (Prf. 284)        | 2056    | 4510      | YES  |
| DOM               | Dom IX7TW (Prf. 285)        | 2057    | 4511      | YES  |
| DOM               | Dom IX7TW (Prf. 288)        | 2094    | 4588      | YES  |
| DOM               | Dom IX7TE (Prf. 278)        | 2089    | 4568      | YES  |
| DOM               | Dom IX7TE (Prf. 274)        | 2090    | 4569      | YES  |
| DOM               | Dom IX7TE (Prf. 275)        | 2091    | 4570      | YES  |
| DOM               | Dom IX7TE (Prf. 273)        | 2092    | 4571      | YES  |
| DOM               | Dom IX TWIDO (Prf. 280)     | 2052    | 4506      | YES  |
| DOM               | Dom IX TWIDO (Prf. 281)     | 2053    | 4507      | YES  |
| DOM               | Dom IX TECO (Prf. 270)      | 2087    | 4566      | YES  |
| DOM               | Dom IX TECO (Prf. 271)      | 2088    | 4567      | YES  |

## CODE PROGRAM

**NEW**

| Lock Manufacturer | Lock-system          | New SSN | Data Card |  |
|-------------------|----------------------|---------|-----------|---|
| HON               | HON (5P)             | 4897    | 4574      | NO  |
| FCV               | FCV Stiftsatz B (5P) | 4898    | 4579      | NO  |
| FCV               | FCV Stiftsatz B (6P) | 4899    | 4579      | NO  |

| <b>IDEA PROGRAM</b> |                     |                      |                |                  | <b>NEW</b>  |
|---------------------|---------------------|----------------------|----------------|------------------|---|
| <b>Lock</b>         | <b>Manufacturer</b> | <b>Lock-system</b>   | <b>New SSN</b> | <b>Data Card</b> |  |
|                     | ABLOY               | Abloy (AY1) - DX_15° | 525            | 4580             | NO  |
|                     | ABLOY               | Abloy (AY1) - SX_15° | 526            | 4582             | NO  |



November 2018 (FOR ALL SKP SUBSCRIBERS)

3\_2018 - SILCA KEY PROGRAMS v. 21.10.x.x

## Silca Key Programs UPGRADE 3/2018





For any info regarding the 3/2018 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.



September 2018 (FOR SKP WEB SUBSCRIBERS)

2\_2018 - SILCA KEY PROGRAMS v. 21.9.2.x

| TRIAIX / QUATTROCODE |                                      |         |           |   | NEW |
|----------------------|--------------------------------------|---------|-----------|---|-----|
| Lock Manufacturer    | Lock-system                          | New SSN | Data Card |  |     |
| A.P.FER              | Astral W39                           | 2064    | 1414      | YES   |     |
| A.P.FER              | Astral W39                           | 2065    | 1414      | YES   |     |
| M&T                  | Astral W41                           | 2066    | 1414      | YES   |     |
| M&T                  | Astral W41                           | 2067    | 1414      | YES   |     |
| YALE                 | Superior 1 Star 10 Pin               | 2068    | 4541      | NO  |     |
| YALE                 | Platinum 3 Star 10 Pin               | 2069    | 4541      | NO  |     |
| HUGO                 | HUGO GR 5S                           | 2076    | 4548      | NO  |     |
| SECUREMME            | SECUREMME K3.3 (5+5)                 | 2077    | 4551      | NO  |     |
| KASSEL               | NF 11 (6+5)                          | 2078    | 4552      | NO  |     |
| DOM                  | Dom IX Twinstar (Prof. 298)          | 2070    | 4542      | YES   |     |
| DOM                  | Dom IX Twinstar Std. Cut (Prof. 298) | 2071    | 4543      | YES   |     |
| DOM                  | Dom IX Twinstar Prf. Cut (Prof. 298) | 2072    | 4544      | YES   |     |
| DOM                  | Dom IX Twinstar (Prof. 299)          | 2073    | 4545      | YES   |     |
| DOM                  | Dom IX Twinstar Std. Cut (Prof. 299) | 2074    | 4546      | YES   |     |
| DOM                  | Dom IX Twinstar Prf. Cut (Prof. 299) | 2075    | 4547      | YES   |     |

| CODE PROGRAM      |             |         |           |   | NEW |
|-------------------|-------------|---------|-----------|---|-----|
| Lock Manufacturer | Lock-system | New SSN | Data Card |  |     |
| CCC               |             | 4882    | 4460      | NO  |     |
| KEYA              |             | 4881    | 4516      | NO  |     |
| UEME              |             | 4883    | 4518      | NO  |     |
| SOPRANO           |             | 4884    | 4519      | NO  |     |
| WELKA             |             | 4885    | 4520      | NO  |     |
| BULLDOG           |             | 4886    | 4521      | NO  |     |
| CISA              |             | 4887    | 4522      | NO  |     |
| SOPRANO           | S-60        | 4888    | 4523      | NO  |     |
| SOPRANO           | S-25        | 4889    | 4524      | NO  |     |
| RIELDA            | RS3         | 4451    | 3756      | YES   |     |
| EVERGOOD          |             | 4890    | 4526      | NO  |     |
| SOBINCO           |             | 4891    | 4527      | NO  |     |
| KEYA              | -           | 4892    | 4532      | NO  |     |
| CORNI             | CC8         | 4894    | 4533      | NO  |     |
| STAM              |             | 4534    | 4893      | NO  |     |

## Silca Key Programs




### Bug fixed

- Silca Software Interface ( SSI ) : solved a bug loading DAT file with minor cuts than the card has
- SKP installation : solved a bug during installation of Windows 32 bit version


## TRIAX / QUATTROCODE

**NEW**

| Lock Manufacturer | Lock-system                        | New SSN | Data Card |  |
|-------------------|------------------------------------|---------|-----------|---|
| SILCA             | Silca SK3 side                     | 2010    | 4395      | NO  |
| SILCA             | Silca SK3 back side                | 2012    | 4407      | NO  |
| FLEXON            | FLEXON CS2100 (6P)                 | 2027    | 4351      | NO  |
| FLEXON            | FLEXON CS2001 (5+5)                | 2028    | 4458      | NO  |
| HYUNDAI           | Hyundai (2T- 8W)                   | 2037    | 3336      | NO  |
| M&T               | M&T Champions Pro CP4 (C6LVJ2)     | 2034    | 3802      | YES   |
| M&T               | M&T Champions Pro CP4 (C6LJ2)      | 1738    | 3802      | YES   |
| M&T               | M&T Champions Pro CP4 (C6LJK)      | 1739    | 3802      | YES   |
| KABA              | Kaba K86 - matrix plus Dealer Code | 2030    | 4464      | YES   |
| KABA              | Kaba K91 - entro Dealer Code       | 2031    | 4467      | YES   |
| KABA              | Kaba K86 - matrix plus             | 2032    | 4468      | YES   |
| KABA              | Kaba K91 - entro                   | 2033    | 4469      | YES   |
| M&C               | M&C Condor (Snake)                 | 2022    | 4428      | YES   |
| M&C               | M&C Condor (Side)                  | 2023    | 4429      | YES   |
| M&C               | M&C Condor Mirror                  | 2038    | 4435      | YES   |
| M&C               | M&C Condor Mirror                  | 2039    | 4435      | YES   |
| M&C               | M&C Condor Mirror                  | 2040    | 4435      | YES   |
| M&C               | M&C Condor Mirror                  | 2041    | 4435      | YES   |
| M&C               | M&C Condor Mirror                  | 2042    | 4435      | YES   |
| M&C               | M&C Condor Mirror                  | 2044    | 4435      | YES   |
| M&C               | M&C Condor Mirror                  | 2045    | 4435      | YES   |
| M&C               | M&C Condor Mirror                  | 2046    | 4435      | YES   |
| M&C               | M&C Condor Mirror                  | 2047    | 4435      | YES   |
| M&C               | M&C Condor Mirror                  | 2048    | 4435      | YES   |
| M&C               | M&C Condor Mirror (Main+snake)     | 2049    | 4438      | YES   |
| M&C               | M&C Condor Mirror (Main+side)      | 2050    | 4440      | YES   |
| M&C               | M&C Condor Mirror (Main pins)      | 2051    | 4443      | YES   |
| M&C               | M&C Condor Mirror (Snake)          | 2058    | 4444      | YES   |
| M&C               | M&C Condor Mirror (Side)           | 2059    | 4445      | YES   |
| M&C               | M&C Condor Mirror (Snake+Side)     | 2060    | 4512      | YES   |
| ISEO              | R11 PROGRESS (SGE)                 | 2061    | 1597      | YES   |
| DOM               | Dom IX TWIDO (Prf. 280)            | 2052    | 4506      | YES   |
| DOM               | Dom IX TWIDO (Prf. 281)            | 2053    | 4507      | YES   |
| DOM               | Dom IX TWIDO (Prf. 282)            | 2054    | 4508      | YES   |




|     |                         |      |      |     |
|-----|-------------------------|------|------|-----|
| DOM | Dom IX TWIDO (Prf. 283) | 2055 | 4509 | YES |
| DOM | Dom IX TWIDO (Prf. 284) | 2056 | 4510 | YES |
| DOM | Dom IX TWIDO (Prf. 285) | 2057 | 4511 | YES |

| CODE PROGRAM      |                  |         |           | NEW   |
|-------------------|------------------|---------|-----------|---|
| Lock Manufacturer | Lock-system      | New SSN | Data Card |  |
| IBFM              | Art.2260/60mm    | 4870    | 4470      | NO  |
| IBFM              | Art.2240/40mm    | 4871    | 4471      | NO  |
| IBFM              | Art.2302/OL/54mm | 4872    | 4472      | NO  |
| IBFM              | Art.2215/15mm    | 4873    | 4473      | NO  |
| IBFM              | Art.2220/20mm    | 4874    | 4474      | NO  |
| IBFM              | Art.2225/25mm    | 4875    | 4475      | NO  |
| RIELDA            | RS3              | 4451    | 3756      | YES   |
| ASSA ABLOY        | Assa Abloy C310  | 4880    | 4505      | NO  |
| LSDA              | -                | 4878    | 4493      | NO  |
| LSDA              | -                | 4879    | 4495      | NO  |




May 2018 (FOR ALL SKP SUBSCRIBERS)


2\_2018 - **SILCA KEY PROGRAMS v. 21.9.x.x**


| Silca Key Programs UPGRADE 2/2018   |  |   |
|---|--|---|
|  | For any info regarding the 2/2018 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS. |  |


March 2018 (FOR SKP WEB SUBSCRIBERS)


1\_2018 - SILCA KEY PROGRAMS v. 21.8.0.x


| <b>TRIAX</b>      |                          |         |           |   | <b>NEW</b> |
|-------------------|--------------------------|---------|-----------|---|------------|
| Lock Manufacturer | Lock-system              | New SSN | Data Card |  |            |
| HYUNDAI           | Hyundai Kona (2T-8W)     | 1990    | 4362      | NO  |            |
| Yale              | 987 Plus                 | 1992    | 4365      | NO  |            |
| ABUS              | ABUS BIKE 8N             | 1993    | 4366      | NO  |            |
| Schlage           | C999 Ultra               | 1994    | 4280      | NO  |            |
| ABUS              | ABUS BIKE 6N             | 1995    | 4368      | NO  |            |
| VACHETTE          | V-DIS Courte A           | 1996    | 4369      | NO  |            |
| VACHETTE          | V-DIS Longue B           | 1997    | 3448      | NO  |            |
| VACHETTE          | YALE 1000 EF 6P          | 1998    | 4369      | NO  |            |
| VACHETTE          | V-DIS+                   | 1999    | 4266      | NO  |            |
| GERDA             | GERDA EVO (6+5+5)        | 2002    | 3580      | NO  |            |
| VACHETTE          | Vachette Radial NT       | 1012    | 2712      | YES   |            |
| EUROLOCKS         | dethleffs EU22RP (2T-6W) | 2004    | 4350      | NO  |            |

| <b>QUATTROCODE</b> |                          |         |           |   | <b>NEW</b> |
|--------------------|--------------------------|---------|-----------|---|------------|
| Lock Manufacturer  | Lock-system              | New SSN | Data Card |  |            |
| HYUNDAI            | Hyundai Kona (2T-8W)     | 1990    | 4362      | NO  |            |
| YALE               | 987 Plus                 | 1992    | 4365      | NO  |            |
| ABUS               | ABUS BIKE 8N             | 1993    | 4366      | NO  |            |
| Schlage            | C999 Ultra               | 1994    | 4280      | NO  |            |
| ABUS               | ABUS BIKE 6N             | 1995    | 4368      | NO  |            |
| VACHETTE           | V-DIS Courte A           | 1996    | 4369      | NO  |            |
| VACHETTE           | V-DIS Longue B           | 1997    | 3448      | NO  |            |
| VACHETTE           | YALE 1000 EF 6P          | 1998    | 4369      | NO  |            |
| VACHETTE           | V-DIS+                   | 1999    | 4266      | NO  |            |
| EUROLOCKS          | Dethleffs EU22RP (2T-6W) | 2004    | 4350      | NO  |            |

| <b>VIPER</b>      |                      |         |           |   | <b>NEW</b> |
|-------------------|----------------------|---------|-----------|---|------------|
| Lock Manufacturer | Lock-system          | New SSN | Data Card |  |            |
| Hyundai           | Hyundai Kona (2T-8W) | 4799    | 4362      | NO  |            |

| <b>IDEA</b>              |                    |                |                  | <b>NEW</b>  |
|--------------------------|--------------------|----------------|------------------|---|
| <b>Lock Manufacturer</b> | <b>Lock-system</b> | <b>New SSN</b> | <b>Data Card</b> |  |
| VITAL                    | ASEC-SECURITY      | 586            | 4388             | NO  |
| EUROSPEC                 | Eurospec C 3L      | 587            | 4389             | NO  |

| <b>PRIMA LASER</b>       |                    |                |                  | <b>NEW</b>  |
|--------------------------|--------------------|----------------|------------------|---|
| <b>Lock Manufacturer</b> | <b>Lock-system</b> | <b>New SSN</b> | <b>Data Card</b> |  |
| VITAL                    | ASEC-SECURITY      | 586            | 4388             | NO  |
| EUROSPEC                 | Eurospec C 3L      | 587            | 4389             | NO  |

| <b>CODE PROGRAM</b>      |                    |                |                  | <b>NEW</b>  |
|--------------------------|--------------------|----------------|------------------|---|
| <b>Lock Manufacturer</b> | <b>Lock-system</b> | <b>New SSN</b> | <b>Data Card</b> |  |
| PUNDRA                   | -                  | 4842           | 561              | NO  |
| PUNDRA                   | -                  | 4843           | 561              | NO  |
| PUNDRA                   | -                  | 4844           | 561              | NO  |

February 2018 (FOR SKP WEB SUBSCRIBERS)

1\_2018 - **SILCA KEY PROGRAMS v. 21.7.1.x**

## Silca Key Programs UPGRADE 1/2018

### **WINDOWS®10 BUG**



**Bug fixed**

Silca has solved many issues of Silca Key Programs, OEM CLIENT and Wintransfer in Windows® 10.

These are our suggestions:

- Upgrade Windows® 10 to the latest version: 1709.xxxx
- Install SKP **version 21.7.1.54** or later via WEB or by DVD

**Note :** the **OEM CLIENT** customers will receive a DVD with **version 3.0.0.5** that solves many issues related to the program and not only specific of Windows® 10 Operative System.



January 2018 (FOR ALL SKP SUBSCRIBERS)

1\_2018 - SILCA KEY PROGRAMS v. 21.7.x.x

## Silca Key Programs UPGRADE 1/2018





For any info regarding the 1/2018 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.





**November 2017 (FOR ALL SKP SUBSCRIBERS)**

**3\_2017 - SILCA KEY PROGRAMS v. 21.6.x.x**

| Silca Key Programs UPGRADE 3/2017   |   |   |
|---|---|---|
|  | <p>For any info regarding the 3/2017 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.</p> |  |

**November 2017 (FOR SKP WEB SUBSCRIBERS)**

**2\_2017 - SILCA KEY PROGRAMS v. 21.5.5.x**


|  <b>Triax / QCODE family</b> |                                |            |           |   |
|--|--------------------------------|------------|-----------|---|
| Lock Manufacturer  | Lock-system                    | New SSN    | Data Card |  |
| ABUS   | Abus EC660                     | Series C-Z | 4063      | YES   |
| AGENT  | Agent NEW GMD-500(5+5+5)       | 1967       | 4329      |   |
| APECS  | APECS RT-110(50/60C)-C-G (6P)  | 1929       | 4297      |   |
| A.P.FER  | A.P.FER CHAMPIONS PRO (CP4-JP) | 1893       | 3802      | YES   |
| ASEC-Security  | ASEC 6P Dimple                 | 1921       | 4286      |   |
| BMW  | BMW (2T-8W)                    | 1890       | 1842      |   |
| CES  | POLLUX WZ (6+5+6)              | 1935       | 4303      | YES   |
| CES  | POLLUX WZ (7+6+7)              | 1936       | 4304      | YES   |
| CISA   | CISA AP4 Pmec-C KA             | 1861       | 4230      | YES   |
| CISA   | CISA AP4 Pmec-A KA             | 1862       | 4230      | YES   |
| CISA   | CISA AP4 Pmec-9 KA             | 1863       | 4230      | YES   |
| CISA   | CISA AP4 Pmec-6 KA             | 1864       | 4230      | YES   |
| CISA   | CISA AP4 Pmec-5 KA             | 1865       | 4230      | YES   |
| CISA   | CISA AP4 Pmec-3 KA             | 1866       | 4230      | YES   |
| CISA   | CISA AP4 Pmec-C CA             | 1970       | 4230      | YES   |
| CISA   | CISA AP4 Pmec-A CA             | 1971       | 4230      | YES   |
| CISA   | CISA AP4 Pmec-9 CA             | 1972       | 4230      | YES   |
| CISA   | CISA AP4 Pmec-6 CA             | 1973       | 4230      | YES   |
| CISA   | CISA AP4 Pmec-5 CA             | 1974       | 4230      | YES   |
| CISA   | CISA AP4 Pmec-3 CA             | 1975       | 4230      | YES   |



|              |                              |      |      |     |
|--------------|------------------------------|------|------|-----|
| DOM          | Dom Sigma Plus (Prof. 146)   | 1926 | 4294 | YES |
| ELZETT       | X11 (6+3+2)                  | 1887 | 4262 |     |
| FAB          | FAB (2T-4W)                  | 1891 | 4265 |     |
| FORD         | FORD HU101 (2T-10W)          | 1956 | 4320 |     |
| GEVY         | GEVY 5 PINS                  | 1924 | 4290 |     |
| GEVY         | GEVY 6 PINS                  | 1925 | 4292 |     |
| GEVY         | GEVY 11 PINS                 | 1927 | 4293 |     |
| HUF-FAB      | VAG Mid (4T-9W+3W)           | 1706 | 4105 |     |
| HUF-FAB      | VAG High (4T-10W+4W)         | 1892 | 4264 |     |
| HUGO         | HUGO GR 4S                   | 1919 | 4284 |     |
| HUGO         | HUGO GR 3.5S                 | 1920 | 4285 |     |
| IBFM         | IBFM 2304/CS                 | 1932 | 4300 |     |
| IBFM         | IBFM 2306                    | 1934 | 4302 |     |
| IBFM         | IBFM 2309                    | 1933 | 4301 |     |
| INAFER       | INAFER (5P+6P)               | 1917 | 4280 |     |
| KIA          | Kia (2T-- 8W)                | 1886 | 4129 |     |
| KIA          | Kia (2T-- 8W)                | 1916 | 3336 |     |
| MAGNUM       | Magnum 6P                    | 1930 | 4299 |     |
| M&C          | M&C Condor (snake+side pins) | 1957 | 4319 | YES |
| MG MONTI     | MG ST-K09                    | 1889 | 4263 | YES |
| MUL.T.LOCK   | Mul.T.Lock interactive       | 1894 | 4267 |     |
| OGDEN        | Ogden Axial 45 (7P)          | 1789 | 446  | YES |
| OGDEN        | Ogden Axial 40 (7P)          | 1790 | 445  | YES |
| PREFER       | Prefer A                     | 1885 | 4261 |     |
| PREFER       | Prefer AA                    | 1883 | 4259 |     |
| PREFER       | Prefer DAA                   | 1882 | 4252 |     |
| PREFER       | Prefer EAA                   | 1884 | 4260 |     |
| PREFER       | Prefer GAB                   | 1880 | 3941 |     |
| PREFER       | Prefer HAA                   | 1881 | 4250 |     |
| RAV-BARRIACH | LOXIS/ILA                    | 1928 | 4296 |     |
| SUPERLOCK    | Superlock SL 11/15           | 1918 | 4281 |     |
| TITAN        | Titan K5-K55/CR T75 (275)    | 1931 | 2570 |     |
| TRIMARK      | TriMark (2T-6W)              | 1888 | 4203 |     |






|      |           |      |      |  |
|------|-----------|------|------|--|
| YALE | Yale 2100 | 1895 | 4266 |  |
|------|-----------|------|------|--|

At the moment the systems are not available on Triax-e.code and Triax 2 due lack of internal board memory.

| Triax / QCODE family  | Modified SSN                                    | Key-system               | Brand |
|---|---|--------------------------|-------|
| <br><b>Bug fixed</b> | Modified distance of the first cut from the Tip |                          |       |
|   | 1827  | Mercedes HU126T (2T-10W) | HUF   |

|  <b>Viper</b> |                     |         |           |   |
|---|---------------------|---------|-----------|---|
| Lock Manufacturer   | Lock-system         | New SSN | Data Card |  |
| KIA   | Kia (2T-- 8W)       | 1887    | 4129      |   |
| BMW   | BMW (2T-8W)         | 4807    | 1842      |   |
| FAB   | FAB (2T-4W)         | 4808    | 4265      |   |
| KIA   | Kia (2T - 8W)       | 4809    | 3336      |   |
| Ford  | FORD HU101 (2T-10W) | 4810    | 4320      |   |



| Viper   | Modified SSN                         | Key-system                   | Brand |
|---|--------------------------------------|------------------------------|-------|
| <br><b>Bug fixed</b> | Solved a problem related to decoding |                              |       |
|   | 850                                  | Clio 3 (1T-6W) Emergency key | HUF   |

|  <b>Unocode299/399/PRO family and UC199</b> |                 |         |           |   |
|---|-----------------|---------|-----------|---|
| Lock Manufacturer   | Lock-system     | New SSN | Data Card |  |
| UAP   | UAP Kinetica    | 4819    | 4246      |   |
| UAP   | UAP 35mm cyl.   | 4820    | 4246      |   |
| PUDRA   | -               | 4821    | 561       |   |
| WILKA   | Wilka TH6 PR100 | 4822    | 2952      |   |
| GREATWALL   | -               | 4823    | 4251      |   |
| YALE  | Yale Jixin      | 4824    | 4253      |   |



|          |                            |      |      |     |
|----------|----------------------------|------|------|-----|
| CDP      | -                          | 4825 | 4254 |     |
| BAB      | -                          | 4826 | 4255 |     |
| GELEM    | SP148                      | 4827 | 4256 |     |
| TONYON   | TY330                      | 4828 | 4257 |     |
| TRELOCK  | MS 506                     | 4829 | 4258 |     |
| TRELOCK  | MS 506                     | 4830 | 4258 |     |
| DOM      | Dom Sigma Plus (Prof. 146) | 4831 | 4295 | YES |
| IBFM     | IBFM SERIE 2300            | 4832 | 594  |     |
| FORD AUS | -                          | 4834 | 4337 |     |


August 2017 (FOR SKP WEB SUBSCRIBERS) 2\_2017

**SILCA KEY PROGRAMS v. 21.5.2.x**

| Triax / QCODE family  |  | New SSN | Key-system                    | Brand      |
|---|---|---------|-------------------------------|------------|
|  | YES   | 1872    | Securystar Extra Safe (6+6+6) | SECURYSTAR |

(\*) At the moment the system is not available on Triax-e.code and Triax 2 due lack of internal board memory.

| Triax / QCODE family   | Modified SSN  | Key-system         | Brand |
|--|---|--------------------|-------|
| <br>Bug fixed | Modified cutting path   |                    |       |
|  |  256 | Evva 3KS-3KS+ (1T) | EVVA  |

| Silca Key Program   |  |
|---|--|
| <br>Bug fixed | Corrected a problem related to cards manual adjustments        |
|   | Solved problem in the Codemaker function related to the J1 jaw |



July 2017 (FOR ALL SKP SUBSCRIBERS)

2\_2017 - **SILCA KEY PROGRAMS v. 21.5.x.x**

## Silca Key Programs UPGRADE 2/2017





For any info regarding the 2/2017 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.





May 2017 (FOR SKP WEB SUBSCRIBERS) 1\_2017

**SILCA KEY PROGRAMS v. 21.4.1.x**

| Triax / QCODE family  |  | New SSN         | Key-system                              | Brand      |
|---|---|-----------------|---|------------|
|  |   | 1841            | Yale YA99R (6+6)                        | YALE       |
|   | YES   | 1849            | Keso K8000 Omega^2 Syst. 9 / Var. 44    | KESO       |
|   | YES   | 1847            | Keso K8000 Omega^2 (right frontprofile) | KESO       |
|   |   | 1543            | Mul.T.Lock Gardesa Tiger (7P)           | MUL.T.LOCK |
|   |   | 1845            | Mul.T.Lock interactive (223)            | MUL.T.LOCK |
|   |   | 1846            | Mul.T.Lock interactive (248)            | MUL.T.LOCK |
|   |   | 646             | Mul.T.Lock Junior/Classic               | MUL.T.LOCK |
|   |   | 1844            | Mul.T.Lock Gardesa Lion                 | MUL.T.LOCK |
|   |   | 1843            | Mul.T.Lock integrator                   | MUL.T.LOCK |
|   | YES   | 1848            | Evva 4KS (1T)                           | EVVA       |
|   |   | 1850            | HOK HOK2R (6P)                          | HOK        |
|   | YES   | 1851            | CISA AP4 PG                             | CISA       |
|   | YES   | 1853            | CISA AP4 PG 3L                          | CISA       |
|   | YES   | 1854            | CISA AP4 PG 3C                          | CISA       |
|   | YES   | 1855            | CISA AP4 PG CA                          | CISA       |
|   | YES   | 1856            | CISA AP4 PG P/S                         | CISA       |
|   | YES   | 1852            | CISA AP4 PE                             | CISA       |
|   | YES   | 1857            | CISA AP4 PE 3L                          | CISA       |
|   | YES   | 1858            | CISA AP4 PE 3C                          | CISA       |
|   | YES   | 1859            | CISA AP4 PE CA                          | CISA       |
| YES   | 1860  | CISA AP4 PE P/S | CISA                                    |            |

(\*) At the moment the system is not available on Triax-e.code and Triax 2 due lack of internal board memory.

| Unocode299/399/PRO family and UC199   |  | New SSN | Key-system    | Brand      |
|---|---|---------|---------------|------------|
|  | YES   | 4214    | RPS+          | WINKHAUS   |
|   |   | 4221    | Cylinder VIP+ | ASSA-ABLOY |
|   |   | 3719    | HDI+/VMI+     | VACHETTE   |
|   |   | 4216    | Cylinder VMI  | ASSA-ABLOY |

April 2017 (FOR SKP WEB SUBSCRIBERS) 1\_2017

**SILCA KEY PROGRAMS v. 21.4.0.x**

## Silca Transponder Program

**Silca Transponder Program has been updated with 120 new vehicle applications.**

















### Managing T80 transponders



As from this version the RW4 PLUS and FASTCOPY PLUS devices can manage the new Silca T80 transponder to be used for:

- Copying keys with Texas® Crypto 80 bit Toyota® transponders.
- Generating Texas® Crypto 80 bit transponders.

**This RW4 PLUS/FASTCOPY PLUS software version also requires the internal C-Box module (version 329) to be updated; see further details in the device handbook and the information given in the on-line guide of "Silca Remote Service".**

| Triax / QCODE family   | New SSN  | Key-system | Brand |
|--|--|------------|-------|
|       |  1770  | Vela 1000  | ABUS  |
|  |  1775 | Vela 2000  | ABUS  |
|  |  1830 | XP20S      | ABUS  |
|  |  1826 | Condor     | M&C   |
|  |  1832 | Condor     | M&C   |
|  |  1833 | Condor     | M&C   |
|  |  1834 | Condor     | M&C   |
|  |  1835 | Condor     | M&C   |
|  |  1836 | Condor     | M&C   |
|  |  1837 | Condor     | M&C   |
|  |  1838 | Condor     | M&C   |
|  |  1839 | Condor     | M&C   |
|  1840 | Condor   | M&C        |       |

(\*) At the moment the system is not available on Triax-e.code and Triax 2 due lack of internal board memory.

| Unocode299/399/PRO family and UC199   | New SSN/Card  | Key-system    | Brand      |
|---|---|---------------|------------|
|  |  4451/3756 | RS3           | RIELDA     |
|   | 4805/4059   | KeyMark X4 7P | MEDECO     |
|   | 4806/4213   | C300          | ASSA-ABLOY |
|   | 4547/3864   |               | MITSUBISHI |



March 2017 (FOR ALL SKP SUBSCRIBERS)

1\_2017 - **SILCA KEY PROGRAMS v. 21.3.x.x**

## Silca Key Programs UPGRADE 1/2017






For any info regarding the 1/2017 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.





December 2016 (FOR ALL SKP SUBSCRIBERS)


3\_2016 - **SILCA KEY PROGRAMS v. 21.2.x.x**


| Silca Key Programs UPGRADE 3/2016   |  |   |
|---|--|---|
|  | For any info regarding the 3/2016 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS. |  |

| Quattrocode / Triax 2 / Triax-e.code  |  |
|---|--|
|  | <p>A new <b>R30</b> clamp that can house FUTURA removable jaws has been introduced for the <b>QUATTROCODE and TRIAX-e.code key-cutting machines</b>. The R30 clamp is necessary only for the new lock systems developed by SILCA with new jaws.</p> <p>All existing options for QUATTROCODE and TRIAX-e.code will not be replaced by removable jaws for the R30 clamp.</p> |


| Triax Quattro  |   |
|--|---|
|  | <p>A <b>R30</b> clamp that can house Triax PRO removable jaws has been introduced for the <b>TRIAX QUATTRO key-cutting machine</b>. All lock systems developed on the removable jaws of TRIAX PRO can also be used with the R30 clamp on the TRIAX QUATTRO.</p> |


| Triax family  |  |
|---|--|
|  | <p>To use the <b>R30 clamp with the TRIAX-e.code, TRIAX 2 and TRIAX QUATTRO key-cutting machines</b>, replace the U102TT and U103TT tracers on the Tracer Tower with a single O4TT tracer. The necessary instructions are included in the box of the optional R30 clamp (D746897ZB).</p> |


| Triax 2 / Triax-e.code  |   |
|---|---|
|  | <p><b>TRIAX-e.code e TRIAX 2: the machine memory is full.</b></p> <p>This update implements all the lock systems already available on the QUATTROCODE, TRIAX QUATTRO and TRIAX PRO key-cutting machines. These systems and the new ones to be developed by Silca will be included <b>ONLY</b> in Silca Key Programs and not incorporated into the machines. <u>Therefore, Silca Key Programs is necessary to use the new systems with the <b>TRIAX-e.code and TRIAX 2 key-cutting machines</b>.</u></p> |

| Triax Pro   |   |
|---|---|
|  | <p>All lock systems that can be used with the standard R29-01J-02J clamp have been implemented.</p> |



| Triax PRO   | Modified SSN                                      | Key-system                               | Brand |
|---|---|--|-------|
| <br><b>Bug fixed</b> | Solved a problem related to the cutting algorithm |  |       |
|   | 60  | Kaba Titan-Aura-Combi (K22-K32-K33)      | KABA  |
|   | 19  | Kaba Titan-Titan Combi-Aura(K22-K32-K33) | KABA  |

| Triax / QCODE family  | Modified SSN  | Key-system                          | Brand |
|---|---|-------------------------------------|-------|
| <br><b>Bug fixed</b> | Corrected code table in according with manufacturer's specifications. |                                     |       |
|   | 🔒 1235  | Iseo R50 Cantiere (Chiave Cantiere) | ISEO  |

| Unocode Pro   |  |  |  |
|---|--|--|--|
| <br><b>Bug fixed</b> | Problem solved in "PC queue" when a number of passages are used to cut the key |  |  |

November 2016 (for SKP Web subscribers) **2\_2016 - SILCA KEY PROGRAMS v. 21.1.3.x**

## Only for Triax PRO

The following systems are available with the new jaws:



| New SSN | Key-system                          | Clamp       | Brand    |
|---------|-------------------------------------|-------------|----------|
| 191     | 4SE MC10R (6P)                      | R29-62J-63J | MCM      |
| 201     | 450 (FT500)                         | R29-64J-65J | FICHET   |
| 202     | 480 (FT510)                         | R29-64J-65J | FICHET   |
| 526     | X-TRA (5+5)                         | R29-80J-81J | WINKHAUS |
| 703     | X-TRA Inclined (5P)                 | R29-80J-81J | WINKHAUS |
| 1049    | Logic 17 (5+5)                      | R29-66J-67J | FIAM     |
| 1050    | Logic 18/19 (5+5)                   | R29-66J-67J | FIAM     |
| 1058    | Template                            | R29-68J-69J | SILCA    |
| 1101    | Twin 6000 (5P)                      | R29-70J-71J | ASSA     |
| 1343    | D20 (6+7)                           | R29-72J-73J | ABUS     |
| 1359    | Astral Tekno Special Profiles       | R29-74J-75J | CISA     |
| 1360    | Bricard Serial XP Special Profiles  | R29-74J-75J | CISA     |
| 1559    | Prestige B5                         | R29-76J-77J | LEHMANN  |
| 1613    | ON-tra (P1)                         | R29-78J-79J | WINKHAUS |
| 1614    | ON-tra (P3)                         | R29-78J-79J | WINKHAUS |
| 1616    | ON-tra + (P1-P1)                    | R29-78J-79J | WINKHAUS |
| 1617    | ON-tra + (P1-P2)                    | R29-78J-79J | WINKHAUS |
| 1618    | ON-tra + (P1-P3)                    | R29-78J-79J | WINKHAUS |
| 1619    | ON-tra + (P1-P4)                    | R29-78J-79J | WINKHAUS |
| 1620    | ON-tra + (P1-P5)                    | R29-78J-79J | WINKHAUS |
| 1621    | ON-tra + (P1-P6)                    | R29-78J-79J | WINKHAUS |
| 1622    | ON-tra + (P1-P7)                    | R29-78J-79J | WINKHAUS |
| 1623    | ON-tra + (P1-P8)                    | R29-78J-79J | WINKHAUS |
| 1624    | ON-tra + (P3-P1)                    | R29-78J-79J | WINKHAUS |
| 1625    | ON-tra + (P3-P2)                    | R29-78J-79J | WINKHAUS |
| 1626    | ON-tra + (P3-P3)                    | R29-78J-79J | WINKHAUS |
| 1627    | ON-tra + (P3-P4)                    | R29-78J-79J | WINKHAUS |
| 1628    | ON-tra + (P3-P5)                    | R29-78J-79J | WINKHAUS |
| 1629    | ON-tra + (P3-P6)                    | R29-78J-79J | WINKHAUS |
| 1630    | ON-tra + (P3-P7)                    | R29-78J-79J | WINKHAUS |
| 1631    | ON-tra + (P3-P8)                    | R29-78J-79J | WINKHAUS |
| 1667    | ON-tra (EGS)                        | R29-78J-79J | WINKHAUS |
| 1690    | Astral Tekno CA (Special Profiles)  | R29-74J-75J | CISA     |
| 1691    | Astral Tekno CE P-S (Special Prof.) | R29-74J-75J | CISA     |








| Triax / QCODE family | New SSN  | Key-system                           | Brand     |
|----------------------|----------|--------------------------------------|-----------|
|                      | 1770 (*) | Vela 1000                            | ABUS      |
|                      | 1775 (*) | Vela 2000                            | ABUS      |
|                      | 1776 (*) | I6BM                                 | BASI      |
|                      | 1769 (*) | EVOK22 (11 Pin)                      | SECUREMME |
|                      | 1778 (*) | EVOK64 (11 Pin)                      | SECUREMME |
|                      | 1777 (*) | EVOK64 (10 Pin)                      | SECUREMME |
|                      | 1779 (*) | IX6 SR S (prof. 250/251/252/253/254) | DOM       |













(\*) At the moment the system is not available on Triax-e.code and Triax 2 due lack of internal board memory.

| Unocode299/399/PRO family and UC199   | New SSN/Card  | Key-system                      | Brand           |
|---|---|---------------------------------|-----------------|
|  | 4764/4145   |                                 | RENAULT - DACIA |
|   |  4765/4146 | Matrix                          | M&C             |
|   | 4766/4147   | Triton 5900 Ej CLIQ to UC199    | ASSA            |
|   | 4767/4148   | Triton - 501 Ikke CLIQ to UC199 | RUKO            |
|   | 4768/4149   | Triton Ikke CLIQ to UC199       | TRIO-VING       |
|   | 4769/4151   | AUB system                      | YALE            |


| Triax / QCODE family   | Modified SSN   | Key-system           | Brand       |
|--|--|----------------------|-------------|
| <br>Bug fixed | Changed cutter in according with manufacturer specifications |                      |             |
|  | 1402   | SY55 - C11           | FACCHINETTI |
|  | 1403   | SY30 SY32 SY35 - C11 | FACCHINETTI |


| Triax family  | Modified SSN   | Key-system                 | Brand |
|---|--|----------------------------|-------|
| <br>Bug fixed | Moved the fixed depth during the cutting of the Axis 1.                                  |                            |       |
|   |  1231  | IXGAMMA (Prof.153)(5+3+7P) | DOM   |
|   |  1244 | IXGAMMA (Prof.154)(5+3+7P) | DOM   |
|   |  1245 | IXGAMMA (Prof.155)(5+3+7P) | DOM   |

| Triax Quattro Triax PRO  | Modified SSN   | Key-system            | Brand |
|--|--|-----------------------|-------|
| <br>Bug fixed | On Axis 3, changed cutter and used circular interpolation in according with manufacturer specifications. |                       |       |
|  | 1247   | IX Saturn (5+4+7P)    | DOM   |
|  | 1494   | IX Saturn (Prof. 168) | DOM   |
|  |  1507                 | IXSATS (Prof. 169)    | DOM   |
|  |  1508                 | IXSATS (Prof. 170)    | DOM   |
|  |  1509                 | IXSATS (Prof. 171)    | DOM   |
|  |  1510                 | IXSATS (Prof. 172)    | DOM   |


| Triax PRO  | Modified SSN   | Key-system           | Brand |
|--|--|----------------------|-------|
| <br>Bug fixed | Added the 29R-01J-02J calmp set  |                      |       |
|  |  1032 | 2 in 1 MK (prof 233) | DORMA |
|  |  1215 | 2 in 1 MK (prof 233) | DORMA |
|  |  1461 | T250 (6+5P)          | TITAN |
|  |  1462 | T250 (2T-5W)         | TITAN |
|  | Added the 29R-24J-25J calmp set  |                      |       |
|  | 864  | C3 (5+5)             | LINCE |

## October 2016 (for SKP Web subscribers) 2\_2016 - SILCA KEY PROGRAMS v. 21.1.2.x

| Triax / QCODE family  | Modified SSN   | Key-system                             | Brand |
|---|--|--|-------|
| <br><b>Bug fixed</b> | Fixed the search by code in according with manufacturer specifications |  |       |
|   | 🔒 1688   | Astral Tekno CA                        | CISA  |
|   | 🔒 1689   | Astral Tekno CE P-S                    | CISA  |
|   | 🔒 1690   | Astral Tekno CA (Special Profiles)     | CISA  |
|   | 🔒 1691   | Astral Tekno CE P-S (Special Profiles) | CISA  |


| Triax Pro   | Modified SSN  | Key-system                           | Brand |
|---|---|--------------------------------------|-------|
| <br><b>Bug fixed</b> | Modified movements to avoid "Faulty contact made" when cutting the key back |                                      |       |
|   | 19  | Titan-Titan Combi-Aura (K22-K32-K33) | KABA  |
|   | 60  | Titan-Aura-Combi (K22-K32-K33)       | KABA  |

## September 2016 (for SKP Web subscribers) 2\_2016 - SILCA KEY PROGRAMS v. 21.1.1.x


| Triax / QCODE family  | New SSN    | Key-system                              | Brand      |
|---|------------|---|------------|
|  | 1734 (*)   | Euro Locks EU21P (2T-7/8W)              | EURO LOCKS |
|   | 🔒 1731 (*) | Kaba ExperT Cross S1.0a (K89A)          | KABA       |
|   | 🔒 1732 (*) | Kaba ExperT Cross S1.0am (K89A)         | KABA       |
|   | 🔒 1736 (*) | Kaba ExperT Cross S1.0am (K89A) D. Code | KABA       |
|   | 🔒 1733 (*) | Kaba ExperT Cross S1.0b (K89B)          | KABA       |
|   | 🔒 1735 (*) | Kaba ExperT Cross S1.0bm (K89B)         | KABA       |
|   | 🔒 1737 (*) | Kaba ExperT Cross S1.0bm (K89B) D. Code | KABA       |
|   | 🔒 1738 (*) | M&T Champions Pro CP4 (C6LJ2)           | M&T        |
|   | 🔒 1739 (*) | M&T Champions Pro CP4 (C6LJK)           | M&T        |
|   | 1740       | Mauer Crypto (6+6+6)                    | MAUER      |

(\*) At the moment the system is not available on Triax-e.code and Triax 2 due lack of internal board memory.

| Unocode299/399/PRO family and UC199   | New SSN/Card | Key-system | Brand |
|---|--------------|------------|-------|
|  | 4763/538     |            | HUWIL |

| Triax / QCODE family  | Modified SSN  | Key-system                              | Brand |
|---|---|---|-------|
| <br><b>Bug fixed</b> | Modified data cards in according with manufacturer specifications |   |       |
|   | 🔒 1688  | Cisa Astral Tekno CA                    | CISA  |
|   | 🔒 1690  | Cisa Astral Tekno CA (Special Profiles) | CISA  |

| Triax PRO   | Modified SSN                    | Key-system              | Brand |
|---|---------------------------------|-------------------------|-------|
| <br><b>Bug fixed</b> | Added the 29R-01J-02J calmp set |                         |       |
|   | 🔒 804                           | Dom IX6 SR E (prof 132) | DOM   |

| Viper family  | Modified SSN                                      | Key-system          | Brand |
|---|---|---------------------|-------|
| <br><b>Bug fixed</b> | Solved a problem related to the cutting algorithm |                     |       |
|   | 694   | Ford C-Max (2T-10W) | FORD  |
|   | 1165  | Ford (2T-10W)       | FORD  |
|   | 1513  | Ford (2T-10W )      | FORD  |

July 2016 (for all SKP subscribers)














2\_2016 - **SILCA KEY PROGRAMS v. 21.1.x.x**



## Silca Key Programs UPGRADE 2/2016




For any info regarding the 2/2016 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.



| Triax / QCODE family  | Modified SSN   | Key-system                   | Brand      |
|---|--|------------------------------|------------|
| <br><b>Bug fixed</b> | Modified cutting algorithm in according with manufacturer specifications                 |                              |            |
|   |  1578   | Pro Star-Mobile Code (6+6+6) | SECURYSTAR |
|   | 547  | V-18 (6+6+6)                 | GOAL       |
|   | 1182   | V-18 (7+7+7)                 | GOAL       |
|   | Added codes from 6001 to 6314  |                              |            |
|   | 921  | Cadillac (2T- 8W)            | HUF        |
|   | 766  | Opel - (2T- 8W)              | HUF        |
|   | 984  | Special Opel (2T-8W)         | HUF        |
|   | Improved dimple decoding   |                              |            |
|   |  1417 | Bravus 1000 (Shoulder stop)  | ABUS       |
|   |  1419 | Bravus 3000 (Shoulder stop)  | ABUS       |
|   |  1420 | Bravus 4000 (Shoulder stop)  | ABUS       |
|   |  1536 | Bravus 3000 (Tip stop)       | ABUS       |
|   |  1646 | Bravus 1000 (Tip stop)       | ABUS       |
|   |  1654 | Bravus 4000 (Tip stop)       | ABUS       |
|   |  1418 | Bravus 2000 (Shoulder stop)  | ABUS       |
|   |  1650 | Bravus 2000 (Tip stop)       | ABUS       |
|  1647                | O9   | OXLOC                        |            |
|  1701                | O9,3   | OXLOC                        |            |
|  1700                | O9,2   | OXLOC                        |            |

| QCODE family  | Modified SSN   | Key-system         | Brand    |
|---|--|--------------------|----------|
| <br><b>Bug fixed</b> | Added depths on axis 5 and 6 in according with manufacturer specifications               |                    |          |
|   |  1012 | Vachette Radial NT | VACHETTE |


| Viper family  | Modified SSN                  | Key-system        | Brand |
|---|-------------------------------|-------------------|-------|
| <br><b>Bug fixed</b> | Added codes from 6001 to 6314 |                   |       |
|   | 921                           | Cadillac (2T- 8W) | HUF   |
|   | 766                           | Opel - (2T- 8W)   | HUF   |





June 2016 (for SKP Web subscribers)


1\_2016 - **SILCA KEY PROGRAMS v. 21.0.6.x**

| Triax / QCODE family  | New SSN   | Key-system                  | Brand   |
|---|---|-----------------------------|---------|
|  |  1722(*) | Trelock InX M2 (4T-4W)      | TRELOCK |
|   |  1723(*) | Trelock InX ML2 (4T-4W)     | TRELOCK |
|   | 1707  | Yardeni 6 Master-No cut tip | YARDENI |
|   | 1708  | Yardeni 6 Regular-Cut tip   | YARDENI |
|   | 1709  | Yardeni 6 Master-Cut tip    | YARDENI |

(\*) At the moment the system is not available on Triax-e.code and Triax 2 due lack of internal board memory.

| Unocode299/399/PRO family and uc199   | Modified SSN/card       | Key-system        | Brand      |
|---|-------------------------|-------------------|------------|
| <br><b>Bug fixed</b> | Modified the clamp side |                   |            |
|   | 4752                    | Chiave ridotta 5P | MG (MONTI) |

| Triax / QCODE family  | Modified SSN   | Key-system                   | Brand   |
|---|--|------------------------------|---------|
| <br><b>Bug fixed</b> | Changed cutter in according with manufacturer specifications                             |                              |         |
|   |  256  | Evva 3KS - 3KS+ (1T)         | EVVA    |
|   |  1221 | Evva 3KS (2T)                | EVVA    |
|   |  1300 | Evva 3KS+ (2T)               | EVVA    |
|   | Modified data cards in according with manufacturer specifications                        |                              |         |
|   | 750  | Yardeni 6 Regular-No cut tip | YARDENI |
|   | 1411   | Trelock RS455-H2 (4T-4W)     | TRELOCK |

| Viper family  | Modified SSN                             | Key-system     | Brand            |
|---|--|----------------|------------------|
| <br><b>Bug fixed</b> | Solved a problem related to the decoding |                |                  |
|   | 850                                      | Clio 3 (1T-6W) | VALEO<br>RENAULT |



May 2016




(for SKP Web subscribers)




1\_2016 - **SILCA KEY PROGRAMS v. 21.0.4.x**

## Silca Key Programs UPGRADE



Updated the comparative list.

| Unocode299/399/PRO family and UC199   | New SSN/Card  | Key-system             | Brand      |
|---|---|------------------------|------------|
|  |  4735/4079 | O8,3                   | OXLOC      |
|   |  4736/4080 | O8,2                   | OXLOC      |
|   | 4743/1039   |                        | HUDSON     |
|   | 4744/1039   |                        | HUDSON     |
|   | 4745/1039   |                        | ESP        |
|   | 4746/1039   |                        | ESP        |
|   | 4747/1039   |                        | ESP        |
|   | 4748/1039   |                        | HUDSON     |
|   | 4749/1039   |                        | HUDSON     |
|   | 4750/4101   | Normal key 4 Pins      | MG (MONTI) |
|   | 4751/4101   | Normal key 5 Pins      | MG (MONTI) |
|   | 4752/4102   | Short key 5 Pins       | MG (MONTI) |
|   | 4753/4103   | Simmetrical key 6 Pins | MG (MONTI) |
|   | 4754/561  |                        | ESP        |
|   | 4755/4106   | RF-360                 | BEMA       |

| Triax / QCODE family  | New SSN  | Key-system         | Brand               |
|---|--|--------------------|---------------------|
|  |  1700 | O9,2               | OXLOC               |
|   |  1701 | O9,3               | OXLOC               |
|   |  1702 | O8,2 (4P)          | OXLOC               |
|   |  1703 | O8,3 (4P)          | OXLOC               |
|   | 1704(*)  | Vag HU162T (4T-8W) | VOLKSWAGEN<br>SKODA |
|   | 295  | 5 Pins             | RONIS               |
|   | 269  | 5 Pins             | CODERM              |


(\*) At the moment the system is not available on Triax-e.code and Triax 2 due lack of internal board memory.





May 2016 (for SKP Web subscribers)

1\_2016 - **SILCA KEY PROGRAMS v. 21.0.3.x**

| Silca Transponder Program   | Silca Transponder Program and RW Software Upgrade  |  |
|---|--|--|
|  | New <b>Software Upgrade of RW devices</b> ( ver. 04.01.084 ) on : RW4, RW4 PLUS, FASTCOPY and FASTCOPY PLUS devices. |  |

April 2016 (for SKP Web subscribers) **1\_2016 - SILCA KEY PROGRAMS v. 21.0.2.x**

| Unocode299/399/PRO family and uc199 | Modified SSN/card                        | Key-system | Brand |
|-------------------------------------|--|------------|-------|
|                                     | Solved a problem related to the stop key |            |       |
|                                     | 4408/3623                                | Fab 200 RS | FAB   |

| Silca Transponder Program | Silca Transponder Program and RW Software Upgrade  |  |  |
|---------------------------|--|--|--|
|                           | New <b>Software Upgrade of RW devices</b> ( ver. 04.00.083 ) on : RW4, RW4 PLUS, FASTCOPY and FASTCOPY PLUS devices. |  |  |


April 2016 (for SKP Web subscribers) **1\_2016 - SILCA KEY PROGRAMS v. 21.0.1.x**

| Unocode299/399/PRO family and UC199 | New SSN/Card | Key-system | Brand      |
|-------------------------------------|--------------|------------|------------|
|                                     | 4738/4082    |            | L&F        |
|                                     | 4737/4081    |            | EURO LOCKS |
|                                     | 4734/1643    |            | BURG       |
|                                     | 4741/2888    |            | ANKERSLOT  |
|                                     | 4739/3351    |            | NEMEF      |
|                                     | 4740/3351    |            | NEMEF      |

| Triax e-code/Triax 2 STAND ALONE mode |  |  |  |
|---------------------------------------|--|--|--|
|                                       | The internal memory of this cutting machine is full.<br>All new systems will be available only in the Silca Key Program and not in STAND ALONE mode. |  |  |

| Triax / QCODE family | New SSN | Key-system                             | Brand   |
|----------------------|---------|--|---------|
|                      | 1679    | Champions Pro CP4-CM7                  | MOTTURA |
|                      | 1680    | Champions Pro CP4 Armo-Riarmo          | MOTTURA |
|                      | 1681    | Champions Pro CP4 Matic                | MOTTURA |
|                      | 1682    | Champions Pro CP4 Riarmo Att-Dis       | MOTTURA |
|                      | 1683    | Champions C28 Plus                     | MOTTURA |
|                      | 1684    | Champions C39                          | MOTTURA |
|                      | 1685    | Champions C43 Plus (5+5)               | MOTTURA |
|                      | 1688    | Astral Tekno CA                        | CISA    |
|                      | 1689    | Astral Tekno CE P-S                    | CISA    |
|                      | 1690    | Astral Tekno CA (Special Profiles)     | CISA    |
|                      | 1691    | Astral Tekno CE P-S (Special Profiles) | CISA    |
|                      | 1692    | R7 Extra Cantiere (Cantiere)           | ISEO    |
|                      | 1693    | R7 Extra Cantiere (Padronale)          | ISEO    |
|                      | 1694    | R7 Extra Ricifrabile (Cantiere)        | ISEO    |
|                      | 1695    | R7 Extra Ricifrabile (Padronale 1)     | ISEO    |

|  |        |                                    |            |
|--|--------|------------------------------------|------------|
|  | 🔒 1696 | R7 Extra Ricifrabile (Padronale 2) | ISEO       |
|  | 1697   | DEC261 SKG                         | DORMA-ISEO |

| Triax / QCODE family  | Modified SSN  | Key-system            | Brand       |
|---|---|-----------------------|-------------|
| <br><b>Bug fixed</b> | Corrected a problem related to the cutting algorithm                  |                       |             |
|   | 1001  | Kia - Hyundai (4T-6W) | KIA-HYUNDAI |
|   | 1310  | Kia - Hyundai (4T-6W) | KIA-HYUNDAI |
|   | Corrected code table in according with manufacturer's specifications. |                       |             |
|   | 1499  | D10/D15 (6+7)         | ABUS        |
|   | Decoding enabled  |                       |             |
|   | 1550  | Valeo (2T - 8W)       | VALEO       |

March 2016 (for ALL SKP subscribers)

1\_2016 - **SILCA KEY PROGRAMS v. 21.0.x.x**

## Silca Key Programs UPGRADE 1/2016



For any info regarding the 1/2016 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.



## Triax e-code/Triax 2 STAND ALONE mode





The internal memory of this cutting machine is full.  
All new systems will be available only in the Silca Key Program and not in STAND ALONE mode.


| Triax / QCODE family | Modified SSN   | Key-system                | Brand       |
|----------------------|--|---------------------------|-------------|
|                      | Modified data cards according to manufacturer specifications |                           |             |
|                      | 960  | V-18 (6+6+6)              | GOAL        |
|                      | 1613   | (7+7+7) (7.9mm)           | WEST        |
|                      | 1614   | (5+5) (6.5mm)             | WEST        |
|                      | 1615   | (6+6) (8.0mm)             | WEST        |
|                      | 1618   | New X-Key (7+6+6)         | SHOWA       |
|                      | 2184   | GMD-500 (5+5+5)           | AGENT       |
|                      | 2197   | V-18 Master (12+12+6)     | GOAL        |
|                      | 2491   | D-9 (3+3+3)               | GOAL        |
|                      | 2494   | V-18 Master (14+14+7)     | GOAL        |
|                      | 2839   | Tostem (4T-5W)            | TOSTEM      |
|                      | 2992   | West (6+6) (8.0mm) New    | WEST        |
|                      | 3035   | Kodai (15P)               | NAGASAWA    |
|                      | 3060   | V-18 (7+7+7)              | GOAL        |
|                      | 3223   | Alpha (5+4)               | ALPHA       |
|                      | 3224   | Keylex (5+5+5)            | NAGASAWA    |
|                      | 3477   | Seacuretech (5+5) (2T-3W) | SEACURETECH |
|                      | 3477   | 2000 Series (5+5) (2T-3W) | YALE        |
|                      | 3480   | Seacuretech (5+5)         | SEACURETECH |
|                      | 3480   | 2000 Series (5+5)         | YALE        |
|                      | 3531   | Tostem (4T-7W)            | TOSTEM      |
|                      | 3732   | West (3+3) (8mm)          | WEST        |
|                      | 3734   | Agent (6+6)               | AGENT       |
|                      | 3735   | West (8+8) (8.0mm)        | WEST        |
|                      | 3736   | West (5+5) (6.5mm) New    | WEST        |
|                      | 3874   | W2-DAC (4T-4W)            | SHOWA       |



**Bug fixed**

| QCODE family  | Modified SSN                             | Key-system        | Brand |
|---|--|-------------------|-------|
| <br><b>Bug fixed</b> | Solved a problem related to the decoding |                   |       |
|   | 34                                       | Sea (4T-5W)       | SEA   |
|   | 35                                       | Sea 20/23 (4T-5W) | SEA   |
|   | 157                                      | Sea 3 (4T-5W)     | SEA   |
|   | 297                                      | Sea 2 (4T-5W)     | SEA   |

| Viper family  | Modified SSN   | Key-system | Brand |
|---|--|------------|-------|
| <br><b>Bug fixed</b> | Modified data cards according to manufacturer specifications |            |       |
|   | 2074   |            | B&S   |

| Prima Laser/Idea family  | Modified SSN  | Key-system  | Brand     |
|--|---|-------------|-----------|
| <br><b>Bug fixed</b> | Added code table in according with manufacturer's specifications.     |             |           |
|  | 579   | 6601        | MOBELLA   |
|  | Corrected code table in according with manufacturer's specifications. |             |           |
|  | 434   | TrioVing 17 | TRIO-VING |
|  | 513   | TrioVing_17 | TRIO-VING |

January 2016 (for SKP Web subscribers)


3\_2015 - **SILCA KEY PROGRAMS v. 20.8.1.x**






| Unocode299/399 family and UC199 | New SSN/Card | Key-system    | Brand     |
|---------------------------------|--------------|---------------|-----------|
|                                 | 4635/4016    |               | CHICAGO   |
|                                 | 4636/4017    |               | CRAFTSMAN |
|                                 | 4653/4022    |               | MINDA-HUF |
|                                 | 4654/4037    |               | MINDA-HUF |
|                                 | 4655/4038    |               | MINDA-HUF |
|                                 | 4656/4039    |               | MINDA-HUF |
|                                 | 4657/4040    |               | BURG      |
|                                 | 4658/4041    | Market TAIWAN | FORD      |
|                                 | 4659/4042    | YCF 35-35     | FEDERAL   |
|                                 | 4660/1041    |               | CHICAGO   |
|                                 | 4661/730     | V63           | ABUS      |
|                                 | 4662/729     | Z74           | ABUS      |
|                                 | 4663/4043    | 40/50         | SOFICLEF  |
|                                 | 4664/4015    |               | ILLINOIS  |
|                                 | 4665/4015    |               | ILLINOIS  |
|                                 | 4666/1054    |               | JOFCO     |
|                                 | 4667/1054    |               | NATIONAL  |
|                                 | 4668/1054    |               | NATIONAL  |
|                                 | 4669/1054    |               | NATIONAL  |
|                                 | 4670/4044    | Market TAIWAN | MAZDA     |
|                                 | 4671/1054    |               | NATIONAL  |
|                                 | 4672/1054    |               | NATIONAL  |
|                                 | 4673/666     | Profile G17   | GUARD     |
|                                 | 4674/1054    |               | NATIONAL  |
|                                 | 4675/1054    |               | NATIONAL  |
|                                 | 4676/1054    |               | NATIONAL  |
|                                 | 4677/1054    |               | NATIONAL  |
|                                 | 4678/1054    |               | NATIONAL  |
|                                 | 4679/1041    |               | CHICAGO   |
|                                 | 4680/1041    |               | CHICAGO   |
|                                 | 4681/1041    |               | CHICAGO   |
|                                 | 4682/1041    |               | CHICAGO   |
|                                 | 4683/1041    |               | CHICAGO   |
|                                 | 4684/1041    |               | CHICAGO   |
|                                 | 4685/1041    |               | CHICAGO   |
|                                 | 4686/1041    |               | CHICAGO   |
|                                 | 4687/1041    |               | CHICAGO   |
|                                 | 4688/1041    |               | CHICAGO   |
|                                 | 4689/1041    |               | CHICAGO   |
|                                 | 4690/1041    |               | CHICAGO   |
|                                 | 4691/1041    |               | CHICAGO   |
|                                 | 4692/1041    |               | CHICAGO   |
|                                 | 4693/1041    |               | CHICAGO   |
|                                 | 4694/4018    |               | PUNDRA    |
|                                 | 4695/4018    |               | PUNDRA    |
|                                 | 4696/539     |               | HUWIL     |








|  |           |  |           |
|--|-----------|--|-----------|
|  | 4635/4016 |  | CHICAGO   |
|  | 4636/4017 |  | CRAFTSMAN |


## Triax e-code/Triax 2 STAND ALONE mode

|   |  |
|---|--|
|  | <p>The internal memory of this cutting machine is full.<br/>All new systems will be available only in the Silca Key Program and not in STAND ALONE mode.</p> |
|---|--|

| Triax / QCODE family  | New SSN  | Key-system             | Brand  |
|---|--|------------------------|--------|
|  |  1649 | DWM6 (2T-6W+4+5)       | CES    |
|   |  1651 | DWM6 (2T-6W)           | CES    |
|   |  1652 | DWM5 (2T-5W+4+5)       | CES    |
|   |  1653 | DWM5 (2T-5W)           | CES    |
|   | 1658   | Emergency Key (5+5+4)  | NISSAN |
|   | 1660   | P2                     | WILKA  |
|   | 1661   | PR300Q                 | WILKA  |
|   | 1662   | P3Q                    | WILKA  |
|   | 1663   | 2000 Plus Series (5+5) | YALE   |

| Viper machine   | New SSN   | Key-system    | Brand  |
|---|---|---------------|--------|
|  | 2197  | Market TAIWAN | FORD   |
|   | 2198  |               | ABUS   |
|   | 2199  |               | ABUS   |
|   | 2200  | Market TAIWAN | MAZDA  |
|   | Added code table in according with manufacturer's specifications. |               |        |
|   | 2020  |               | SUBARU |

| Triax / QCODE family  | Modified SSN   | Key-system                               | Brand |
|---|--|--|-------|
| <br><b>Bug fixed</b> | Returned to the standard decoding  |  |       |
|   | 57   | Keso K2000 Syst. 3 / Var. 4 (5 Axis)     | KESO  |
|   | 273  | Keso K2000S Syst. 4 / Var. 3 (3 Axis)    | KESO  |
|   | 673  | Keso K2000S Omega Syst. 4/Var. 13 (3mm)  | KESO  |
|   |  1158 | Keso K4000 Omega Syst. 7 / Var. 39       | KESO  |
|   | 1298   | Keso K2000 Syst. 3/Var. 4 (5mm)          | KESO  |
|   | 1299   | Keso K2000S Omega Syst. 4 / Var. 3 (5mm) | KESO  |
|   |  1466 | Keso K4000 Omega (right frontprofile)    | KESO  |
|   |  1576 | Keso K2500FP (Syst.7 / Var.41)           | KESO  |
|   | 1656   | Keso K10RS (3 Axis)                      | KESO  |
|   | 1657   | Keso K10RS Omega Syst. 4 / Var. 3 (5mm)  | KESO  |

| Prima Laser/Idea family   | Modified SSN   | Key-system  | Brand     |
|---|--|-------------|-----------|
| <br><b>Bug fixed</b> | Modified data cards according to manufacturer specifications |             |           |
|   | 584  | Securmap 11 | SECUREMME |





# SKP PRO WEB Update








December 2015 (for ALL SKP subscribers)

**3\_2015 - SILCA KEY PROGRAMS v. 20.8.x.x**

| Silca Key Programs UPGRADE 3/2015   |  |   |
|---|--|---|
|  | For any info regarding the 3/2015 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS. |  |


| Triax e-code/Triax 2 STAND ALONE mode   |  |
|---|--|
|  | The internal memory of this cutting machine is full.<br>All new systems will be available only in the Silca Key Program and not in STAND ALONE mode. |


| QCODE family  | Modified SSN                                      | Key-system      | Brand   |
|---|---|-----------------|---------|
| <br><b>Bug fixed</b> | Solved a problem related to the cutting algorithm |                 |         |
|   | 261-295-926-607                                   | RS3-Abus EP 10  | VARIOUS |
|   | 303   | Prefer (3+3W)   | PREFER  |
|   | 302   | Prefer (3+3W+2) | PREFER  |


| TRIAx family  | Modified SSN                             | Key-system         | Brand |
|---|--|--------------------|-------|
| <br><b>Bug fixed</b> | Solved a problem related to the decoding |                    |       |
|   | 1348                                     | BMW BW9EHP (4T-4W) | ZADI  |

November 2015 (for SKP Web subscribers)

**2\_2015 - SILCA KEY PROGRAMS v. 20.7.6.x**

| Triax e-code/Triax 2 STAND ALONE mode   |  |
|---|--|
|  | The internal memory of this cutting machine is full.<br>All new systems will be available only in the Silca Key Program and not in STAND ALONE mode. |

| Silca Key Programs  |  |
|---|--|
| <br><b>Bug fixed</b> | Corrected a problem related importing of DAT file for flat keys, with programs SSI |







| Unocode299/399 family and UC199   | Modified Card               | Key-system        | Brand       |
|---|-----------------------------|-------------------|-------------|
| <br><b>Bug fixed</b> | Corrected the space of cut. |                   |             |
|   | 3907                        | Vitess 2000       | PFAFFENHAIN |
|   | 3910                        | Zolit/Vitess 1000 | PFAFFENHAIN |
|   | 3913                        | Vitess 1000       | PFAFFENHAIN |
|   | 3915                        | Zolit/Vitess 2000 | PFAFFENHAIN |
|   | 3916                        | Zolit/Vitess 4000 | PFAFFENHAIN |
|   | 3922                        | Vitess 4000       | PFAFFENHAIN |






November 2015 (for SKP Web subscribers) 2\_2015 - **SILCA KEY PROGRAMS v. 20.7.5.x**

## Triax e-code/Triax 2 STAND ALONE mode



The internal memory of this cutting machine is full.  
All new systems will be available only in the Silca Key Program and not in STAND ALONE mode.

| Triax / QCODE family  | New SSN  | Key-system                     | Brand |
|---|--|--------------------------------|-------|
|  |  1637 | (Pr.169-170-171-172)(Precoded) | INN   |
|   |  1638 | (Prof. 169)                    | INN   |
|   |  1639 | (Prof. 170)                    | INN   |
|   |  1640 | (Prof. 171)                    | INN   |
|   |  1641 | (Prof. 172)                    | INN   |
|   | 1642   | Pacri (5+5)                    | PACRI |
|   | 1643   | 164 DBNE (5+5)                 | KALE  |


| QCODE family  | Modified SSN  | Key-system               | Brand             |
|---|---|--------------------------|-------------------|
| <br><b>Bug fixed</b> | Corrected a problem related to the decoding algorithm                                   |                          |                   |
|   | 302   | Prefer (3+3W)            | PREFER            |
|   | 303   | Prefer (3+3W+2)          | PREFER            |
|   | Corrected a problem related to movement of the cutting                                  |                          |                   |
|   |  261 | RS3/CHIFRAL/EP10 (4+4+5) | ABUS/CISA/BRICARD |
|   |  607 | RS3 75 (4+4+5)           | CISA              |
|   |  925 | EP10 (4+4+5)             | ABUS              |
|   |  926 | EP10 (4+4+5)             | ABUS              |

## Triax e-code/Triax 2



**Bug fixed**

A new machine internal program which solves a generic problem related to the decoding and the carriage speed.

| Unocode299/399 family and UC199   | New SSN/Card | Key-system                     | Brand       |
|---|--------------|--------------------------------|-------------|
|  | 4348/3550    |                                | MIWA        |
|   | 4483/3806    |                                | HONDA       |
|   | 4599/3973    | Market Jap. stop 3             | MITSUBISHI  |
|   | 4600/3974    |                                | MIWA        |
|   | 4601/3975    | Market Japan.                  | MIWA        |
|   | 4602/3976    | ATL4 & ATL5                    | SQUIRE&SONS |
|   | 4603/3979    | KB                             | SQUIRE&SONS |
|   | 4604/3982    |                                | EURO LOCKS  |
|   | 4605/3984    |                                | RONIS       |
|   | 4606/3985    | Chinese market (reversed cuts) | TOYOTA      |
|   | 4607/3987    |                                | MINDA-HUF   |

4608/4003




















HONDA


**October 2015 (for SKP Web subscribers) 2\_2015 - SILCA KEY PROGRAMS v. 20.7.3.x**


## Silca Key Programs UPGRADE



The test of SILCA KEY PROGRAMS with WINDOWS 10 resulted positive.

| Triax / QCODE family   | New SSN  | Key-system               | Brand    |
|--|--|--------------------------|----------|
|  | 1612   | Avocet Pioneer plus (6P) | FEDERAL  |
|  | 1615   | TWO (6P)                 | CORBIN   |
|  |  1613   | ON-tra (P1)              | WINKHAUS |
|  |  1614   | ON-tra (P3)              | WINKHAUS |
|  |  1616   | ON-tra + (P1-P1)         | WINKHAUS |
|  |  1617   | ON-tra + (P1-P2)         | WINKHAUS |
|  |  1618   | ON-tra + (P1-P3)         | WINKHAUS |
|  |  1619   | ON-tra + (P1-P4)         | WINKHAUS |
|  |  1620   | ON-tra + (P1-P5)         | WINKHAUS |
|  |  1621   | ON-tra + (P1-P6)         | WINKHAUS |
|  |  1622  | ON-tra + (P1-P7)         | WINKHAUS |
|  |  1623 | ON-tra + (P1-P8)         | WINKHAUS |
|  |  1624 | ON-tra + (P3-P1)         | WINKHAUS |
|  |  1625 | ON-tra + (P3-P2)         | WINKHAUS |
|  |  1626 | ON-tra + (P3-P3)         | WINKHAUS |
|  |  1627 | ON-tra + (P3-P4)         | WINKHAUS |
|  |  1628 | ON-tra + (P3-P5)         | WINKHAUS |
|  |  1629 | ON-tra + (P3-P6)         | WINKHAUS |
|  |  1630 | ON-tra + (P3-P7)         | WINKHAUS |
|  |  1631 | ON-tra + (P3-P8)         | WINKHAUS |
| 1632   | W551 (4+4+3)   | PREFER                   |          |
| 1633   | S211 (5+5+4)   | PREFER                   |          |
| 1635   | Subaru Emergency Key (2T-4W)   | TOKAI RIKA               |          |


| Viper machine   | New SSN | Key-system                   | Brand      |
|---|---------|------------------------------|------------|
|  | 2194    | Subaru Emergency Key (2T-4W) | TOKAI RIKA |

| Unocode299/399 family and UC199   | New SSN/Card | Key-system | Brand      |
|---|--------------|------------|------------|
|  | 4595/1039    |            | BOMMER     |
|   | 4592/3960    | TE01       | TOKOZ      |
|   | 4593/3961    | EG         | UNION      |
|   | 4585/3935    |            | JPM        |
|   | 4585/3937    |            | SUZUKI     |
|   | 4586/3431    |            | ANKERSLOT  |
|   | 4588/723     |            | EURO LOCKS |
|   | 4589/723     |            | EURO LOCKS |
|   | 4591/1435    |            | EURO LOCKS |
|   | 4592/1643    |            | BURG       |

September 2015 (for SKP Web subscribers)


2\_2015 - **SILCA KEY PROGRAMS v. 20.7.2.x**

| Triax / QCODE family  | New SSN | Key-system | Brand  |
|---|---------|------------|--------|
|  | 1463    | UL20 (6P)  | PREFER |

| Triax / QCODE family  | Modified SSN   | Key-system         | Brand |
|---|--|--------------------|-------|
| <br><b>Bug fixed</b> | Modified data cards according to manufacturer specifications |                    |       |
|   | 20   | K2000 (82D-3A)     | KESO  |
|   | 273  | K2000S (20+20+20)  | KESO  |
|   | 1299   | K2000S Omega (5mm) | KESO  |
|   | Returned to the standard decoding                            |                    |       |
|   | 20   | K2000 (82D-3A)     | KESO  |
|   | 21   | K2000 (90D-3A)     | KESO  |
|   | 105  | 1000/Lips (3A)     | KESO  |
|   | 598  | K1000S (3 Axis)    | KESO  |
|   | 807  | K1000 (3 Axis)     | KESO  |



July 2015 (for SKP Web subscribers)

**2\_2015 - SILCA KEY PROGRAMS v. 20.7.1.x**

| Triax family  | Modified SSN  | Key-system         | Brand      |
|---|---|--------------------|------------|
| <br><b>Bug fixed</b> | Corrected a problem related to movement of the decoding |                    |            |
|   | 1285  | Euro Locks (2T-5W) | EURO LOCKS |


July 2015 (for ALL SKP subscribers)

**2\_2015 - SILCA KEY PROGRAMS v. 20.7.x.x**

| Silca Key Programs UPGRADE 2/2015   |  |   |
|---|--|---|
|  | For any info regarding the 2/2015 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS. |  |

July 2015 (for SKP Web subscribers)


**1\_2015 - SILCA KEY PROGRAMS v. 20.6.4.x**


| Triax / QCODE family  | Modified SSN   | Key-system           | Brand |
|---|--|----------------------|-------|
| <br><b>Bug fixed</b> | Modified data cards according to manufacturer specifications |                      |       |
|   | 393  | IX5 DAS (pf.038/101) | DOM   |
|   | 20   | K2000 (82D-3A)       | KESO  |
|   | 21   | K2000 (90D-3A)       | KESO  |


May 2015 (for SKP Web subscribers)


1\_2015 - SILCA KEY PROGRAMS v. 20.6.2.x

| Triax / QCODE family  | New SSN  | Key-system                   | Brand      |
|---|--|------------------------------|------------|
|  | 1570   | 118 (6P)                     | CHAIRO     |
|   | 1571   | 280/50 (6+6)                 | DURO       |
|   | 1572   | Bmw (2T-8W)                  | HUF        |
|   |  1577 | New Star Guard (6+6+6)       | SECURYSTAR |
|   |  1578 | Pro Star-Mobile Code (6+6+6) | SECURYSTAR |
|   |  1576 | Casa                         | KESO       |

| Triax / QCODE family   | Modified SSN   | Key-system             | Brand       |
|--|--|------------------------|-------------|
| <br>Bug fixed | Modified data cards according to manufacturer specifications |                        |             |
|  | 57   | K2000 (5 Axis)         | KESO        |
|  | 20   | K2000 (3 Axis)         | KESO        |
|  | 21   | K2000S (3 Axis)        | KESO        |
|  | 277  | K2000S (Step-Drilling) | KESO        |
|  | 273  | K2000S (20+20+20)      | KESO        |
|  | 673  | K2000S Omega (3mm)     | KESO        |
|  | 1298   | K2000 (5mm)            | KESO        |
|  | 1299   | K2000S Omega (5mm)     | KESO        |
|  | 598  | K1000S (3 Axis)        | KESO        |
|  | 1264   | NW4 (5P - 2T-5W)       | MAUER / MLS |

| Triax-e.code   | Modified SSN  | Key-system  | Brand |
|--|---|-------------|-------|
| <br>Bug fixed | Fixed entry tip on laser track according to manufacturer specifications |             |       |
|  | 1420  | Bravus 4000 | ABUS  |
|  |   |             |       |

| Unocode299/399 family and UC199   | New SSN/Card | Key-system | Brand   |
|---|--------------|------------|---------|
|  | 4566/561     |            | CHICAGO |
|   | 4568/3890    | DG1        | SARGENT |
|   | 4569/3891    | DG2-DG3    | SARGENT |
|   | 4570/258     |            | GIOBERT |
|   | 4571/3899    | ATK        | AVOCENT |
|   | 4573/3899    |            | WESLOCK |

| Viper machine   | New SSN | Key-system  | Brand |
|---|---------|-------------|-------|
|  | 2184    | Bmw (2T-8W) | HUF   |
|   |         |             |       |
|   |         |             |       |

March 2015 (for all SKP subscribers)

1\_2015 - **SILCA KEY PROGRAMS v. 20.6.x.x**

| Silca Key Programs UPGRADE 1/2015 |  |  |
|-----------------------------------|--|--|
|                                   | For any info regarding the 1/2015 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS. |  |

February 2015 (for SKP Web subscribers)

2\_2014 - **SILCA KEY PROGRAMS v. 20.5.0.x**

| Triax / QCODE family | New SSN | Key-system        | Brand  |
|----------------------|---------|-------------------|--------|
|                      | 1550    | Valeo (2T - 8W)   | TOYOTA |
|                      | 1553    | Palladium (7P)    | VIRO   |
|                      | 1554    | Palladium PV (7P) | VIRO   |

| Triax / QCODE family | Modified SSN   | Key-system                       | Brand |
|----------------------|--|----------------------------------|-------|
| <br>Bug fixed        | Modified cutting algorithm and cutter in according to manufacturer specifications. |                                  |       |
|                      | 747  | 164SN-ST-SK-SM-SR-DSN-OBS S (6P) | KALE  |
|                      | 1545   | SPC F6 (6P)                      | S2    |
|                      |  |                                  |       |

| Viper machine | Modified SSN  | Key-system    | Brand  |
|---------------|---|---------------|--------|
| <br>Bug fixed | Corrected a problem related to movement of the cutting tip. |               |        |
|               | 2177  | Valeo (2T-8W) | TOYOTA |

January 2015 (for SKP Web subscribers)

2\_2014 - **SILCA KEY PROGRAMS v. 20.4.1.x**

| Viper machine | Modified SSN/card   | Key-system    | Brand                                       |
|---------------|---|---------------|---|
| <br>Bug fixed | Corrected a problem related to movement of the cutting tip. |               |   |
|               | 1117  | Valeo (2T-7W) | CITROËN<br>FIAT<br>LANCIA<br>MAN<br>PEUGEOT |

December 2014 (for ALL SKP subscribers)

2\_2014 - **SILCA KEY PROGRAMS v. 20.4.x.x**

| Silca Key Programs UPGRADE 2/2014 |
|-----------------------------------|
|-----------------------------------|





For any info regarding the 2/2014 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS.



## October 2014 (for SKP Web subscribers) 1\_2014 - SILCA KEY PROGRAMS v. 20.3.1.x

| Silca Key Programs      |   |
|-------------------------|---|
| <p><b>Bug fixed</b></p> | Corrected a problem in the SSI related to blank cuts in edge keys |

## September 2014 (for SKP Web subscribers) 1\_2014 - SILCA KEY PROGRAMS v. 20.3.0.x


| Triax / QCODE family    | Modified SSN   | Key-system              | Brand        |
|-------------------------|--|-------------------------|--------------|
| <p><b>Bug fixed</b></p> | Modified data cards according to manufacturer specifications |                         |              |
|                         | 302  | Rbz (3+3W)              | PREFER / RBZ |
|                         | 303  | (3+3W+2)                | PREFER       |
|                         | 88   | Quattro 1.0 (Australia) | KABA         |

| Triax / QCODE family | New SSN | Key-system                       | Brand |
|----------------------|---------|----------------------------------|-------|
|                      | 1520    | ML+ (5+5)                        | MAUER |
|                      | 1521    | Bullit (6P)                      | IBFM  |
|                      | 747     | 164SN-ST-SK-SM-SR-DSN-OBS S (6P) | KALE  |


| Unicode299/399 family and UC199 | New SSN/Card | Key-system | Brand      |
|---------------------------------|--------------|------------|------------|
|                                 | 4481/148     |            | HERO-HONDA |
|                                 | 4482/148     |            | HERO-HONDA |
|                                 | 3436/2222    | S6         | KALE       |
|                                 | 2342/148     |            | HONDA      |











| Lector / Optika | Silca Key Reader Program Upgrade 1/2014   |  |
|-----------------|---|--|
|                 | <p><b>Update with 276 new references.</b><br/>The new references include transponder <b>MH keys, TE Empty Shell keys and FH blades for the Flip keys.</b></p> <p>Remember to use a USB PEN to update the OPTIKA program. To download the USB-PEN use the "Advanced" function in the OPTIKA "Archives =&gt;Machines" of the Key Reader Program (or SKP).</p> |  |




| Silca Transponder Program   | Silca Transponder Program and RW Software Upgrade  |
|---|--|
|  | <p><b>Silca Transponder Program</b> has been updated with 319 new vehicle applications due to the <b>Empty-Shells, MH keys and Flip keys</b>.</p> <p>New <b>Software Upgrade of COM-CODE</b> device ( ver 10.3 ) to manage a new version of Holden-Commodore keys</p> <p>New <b>Software Upgrade of RW devices</b> ( ver 3.14.074 ) : on RW4 devices the Dutch language has been added</p> <p><b>Update the software on</b> : RW4, RW4 PLUS, FASTCOPY, FASTCOPY PLUS and COM-CODE devices.</p> |

**August 2014 (for SKP Web subscribers) 1\_2014 - SILCA KEY PROGRAMS v. 20.2.5.x**

| Triax / QCODE family  | Modified SSN   | Key-system                    | Brand |
|---|--|-------------------------------|-------|
| <br><b>Bug fixed</b> | Modified data cards according to manufacturer specifications |                               |       |
|   | 617  | WSM (5+5+6)                   | CES   |
|   | 1417-1418-1419-1420  | BRAVUS 1000, 2000, 3000, 4000 | ABUS  |


| Triax / QCODE family  | New SSN  | Key-system                               | Brand |
|---|--|--|-------|
|  |  1498 | AP3 PP solo attive                       | CISA  |
|   |  1504 | R9 Country cantiere                      | ISEO  |
|   |  1505 | R9 Country padronale                     | ISEO  |
|   |  1506 | IXSATS (Prof.169-170-171-172) (Precoded) | DOM   |
|   |  1507 | IXSATS (Prof. 169)                       | DOM   |
|   |  1508 | IXSATS (Prof. 170)                       | DOM   |
|   |  1509 | IXSATS (Prof. 171)                       | DOM   |
|   |  1510 | IXSATS (Prof. 172)                       | DOM   |
|   |  1511 | UDM (4P)                                 | CES   |

| Unocode299/399 family and UC199   | New SSN/card    | Key-system         | Brand |
|---|-----------------|--------------------|-------|
|  | 4462/666        | Profile G11        | GUARD |
|   | 4463/666        | Profile G11        | GUARD |
|   | 4464/666        | Profile G11        | GUARD |
|   | 4465/666        | Profile G12        | GUARD |
|   | 4466/666        | Profile G12        | GUARD |
|   | 4467/666        | Profile G12        | GUARD |
|   | 4468/666        | Profile G13        | GUARD |
|   | 4469/666        | Profile G13        | GUARD |
|   | 4470/666        | Profile G13        | GUARD |
|   | 4471/666        | Profile G13        | GUARD |
|   | 4472/666        | Profile G14        | GUARD |
|   | 4473/666        | Profile G14        | GUARD |
|   | 4474/666        | Profile G14        | GUARD |
|   | 4475/666        | Profile G17        | GUARD |
|   | 4476/666        | Profile G17        | GUARD |
|   | 44770/666       | Profile G17        | GUARD |
|   | 4478/666        | Profile G17        | GUARD |
|   | 4479/666        | Profile G17        | GUARD |
|   | 4480/666        | Profile EPS/P EP83 | GUARD |
|   | 3436/2222       | S6                 | KALE  |
| 4460/3785   | Depth 1-2-3-4-5 | MIWA               |       |
| 4461/410  |                 | SCHLAGE            |       |

June 2014



(for SKP Web subscribers)

1\_2014 - **SILCA KEY PROGRAMS v. 20.2.1.x**

| Triax / QCODE family   | Modified SSN   | Key-system      | Brand   |
|--|--|-----------------|---------|
| <br>Bug fixed | Corrected a problem related to the cutting algorithm |                 |         |
|  | 1411   | Trelock (4T-4W) | TRELOCK |



| Triax / QCODE family | New SSN | Key-system | Brand |
|----------------------|---------|------------|-------|
|----------------------|---------|------------|-------|

|   |  |                       |            |
|---|--|-----------------------|------------|
|  | 1494   | IX Saturn (Prof. 168) | DOM        |
|   |  1495 | WSM NEW (5+5+6)       | CES        |
|   | 1496   | C6 (5+5)              | LINCE      |
|   | 1497   | Toyota (2T-4W)        | TOKAY RICA |
|   | 1499   | D10 D15 (6+7)         | ABUS       |

| Unocode299/399 family and UC199  | New SSN/card  | Key-system | Brand            |
|--|---|------------|------------------|
|  | 4454/3768   |            | CHEVROLET-DAEWOO |
|  | 4453/3763   | GR 2.55    | HUGO             |
|  |  4457/3764 | Starry     | STAHLEX          |
|  | 4455/3610   | NW52       | ABUS             |
|  | 4458/3610   | NW52       | ABUS             |
|  | 4456/3611   | NW72       | ABUS             |
|  | 4459/3766   |            | DIN-BOX          |



May 2014 (for All SKP subscribers)

**1\_2014 - SILCA KEY PROGRAMS v. 20.2.x.x**


| Silca Key Programs UPGRADE 1/2014   |  |   |
|---|--|---|
|  | For any info regarding the 1/2014 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS. |  |


December 2013 (for All SKP subscribers)

**3\_2013 - SILCA KEY PROGRAMS v. 20.1.x.x**


| Silca Key Programs UPGRADE 3/2013   |  |   |
|---|--|---|
|  | For any info regarding the 3/2013 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS. |  |


## October 2013 (for SKP Web subscribers) 2\_2013 - SILCA KEY PROGRAMS v. 20.0.3.x

| Silca Transponder Program   | RW Software update  |
|---|---|
| <br><b>Bug fixed</b> | <ul style="list-style-type: none"> <li>- A minor issue was solved for RW SW devices <b>with version 3.10.068</b>. The Generation of a Texas®-Crypto transponder on a GTI transponder has been corrected.</li> </ul> <p>We suggest to upgrade the internal SW of RW4, RW4 PLUS, FASTCOPY, FASTCOPY PLUS devices.</p> |

| Viper machine   | Modified SSN/card  | Key-system           | Brand           |
|---|--|----------------------|-----------------|
| <br><b>Bug fixed</b> | Corrected a problem related to code search after decoding, operating in stand alone  |                      |                 |
|   | 855/950  | Lexus_TOY48P (4T-5W) | TOYOTA<br>LEXUS |
|   | <ul style="list-style-type: none"> <li>- Corrected a problem related to duplicating the key with read measurements (EXACT COPY) after decoding.</li> </ul> |                      |                 |

## October 2013 (for SKP Web subscribers) 2\_2013 - SILCA KEY PROGRAMS v. 20.0.1.x

| Silca Transponder Program   | RW Software update   |
|---|--|
| <br><b>Bug fixed</b> | <ul style="list-style-type: none"> <li>- A minor issue was solved for RW SW devices <b>with version 3.09.066</b>.</li> </ul> <p>We suggest to upgrade the internal SW of RW4, RW4 PLUS, FASTCOPY, FASTCOPY PLUS devices but it's not required.</p> |

| Unocode299/399 family and uc199   | Modified SSN/card                                  | Key-system      | Brand  |
|---|--|-----------------|--------|
| <br><b>Bug fixed</b> | Corrected a problem related to code in list        |                 |        |
|   | 2299/345   | TWIN/V-10 COMBI | Assa   |
|   | Added the new model YAMAHA MAJESTY 250 (Year 2000) |                 |        |
|   | 2083/289   |                 | YAMAHA |

| Unocode299/399 family | New SSN/card | Key-system                 | Brand  |
|-----------------------|--------------|----------------------------|--------|
|                       | 4440/3729    | Only original key (stop 3) | NISSAN |

September 2013 (for SKP Web subscribers) 2\_2013 - **SILCA KEY PROGRAMS v. 20.0.0.x**

| Silca Transponder Program | New function   |  |           |          |    |               |  |    |     |            |    |     |                     |    |     |              |    |    |                    |    |     |        |    |    |        |    |     |        |    |     |               |    |    |           |    |    |               |    |    |                 |
|---------------------------|--|--|-----------|----------|----|---------------|--|----|-----|------------|----|-----|---------------------|----|-----|--------------|----|----|--------------------|----|-----|--------|----|----|--------|----|-----|--------|----|-----|---------------|----|----|-----------|----|----|---------------|----|----|-----------------|
| <br><br><br><br>          | <p><b>a) Copying transponders onto new Silca GTI multi-function transponders</b><br/>           With this version, RW devices can copy the following transponders:</p> <ul style="list-style-type: none"> <li>• Second generation Philips Crypto ID46</li> <li>• Texas Crypto ID60, 61, 62, ... 69, 70, 6A, 6F</li> <li>• Texas fixed code ID4C</li> </ul> <p><b>onto the new Silca GTI** multi-function transponder.</b><br/>           (**) See the updated list of models for which keys can be copied ( Silca vehicle guide and Silca Transponder Program ).</p> <p><b>b) Generating codes on GTI transponders (Pre-setting)</b><br/>           With this RW version used with the “TRP Setting Program” and “Silca Transponder Program”, the transponder codes listed below can be generated on the new Silca GTI multi-function transponder; the resulting GTI transponders must be programmed*** on vehicles by means of a diagnostics device or manual procedure</p> <p style="text-align: center;"><b>Texas Crypto Transponders:</b></p> <table border="1" style="width: 100%;"> <thead> <tr> <th>Silca TRP ID</th> <th>Silca TRP</th> <th>Main Use</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">60</td> <td style="text-align: center;">T7- T13 - T16</td> <td style="text-align: center;">Ford - Nissan- Kia, Hyundai, others...</td> </tr> <tr> <td style="text-align: center;">61</td> <td style="text-align: center;">T19</td> <td style="text-align: center;">Mitsubishi</td> </tr> <tr> <td style="text-align: center;">62</td> <td style="text-align: center;">T21</td> <td style="text-align: center;">Mitsubishi - Subaru</td> </tr> <tr> <td style="text-align: center;">63</td> <td style="text-align: center;">T17</td> <td style="text-align: center;">Ford - Mazda</td> </tr> <tr> <td style="text-align: center;">64</td> <td style="text-align: center;">T8</td> <td style="text-align: center;">Chrysler - Renault</td> </tr> <tr> <td style="text-align: center;">65</td> <td style="text-align: center;">T18</td> <td style="text-align: center;">Suzuki</td> </tr> <tr> <td style="text-align: center;">66</td> <td style="text-align: center;">--</td> <td style="text-align: center;">Suzuki</td> </tr> <tr> <td style="text-align: center;">67</td> <td style="text-align: center;">T31</td> <td style="text-align: center;">Toyota</td> </tr> <tr> <td style="text-align: center;">69</td> <td style="text-align: center;">T22</td> <td style="text-align: center;">Yamaha Cycles</td> </tr> <tr> <td style="text-align: center;">70</td> <td style="text-align: center;">--</td> <td style="text-align: center;">Toyota EU</td> </tr> <tr> <td style="text-align: center;">71</td> <td style="text-align: center;">--</td> <td style="text-align: center;">Suzuki Cycles</td> </tr> <tr> <td style="text-align: center;">72</td> <td style="text-align: center;">--</td> <td style="text-align: center;">Kawasaki Cycles</td> </tr> </tbody> </table> | Silca TRP ID                           | Silca TRP | Main Use | 60 | T7- T13 - T16 | Ford - Nissan- Kia, Hyundai, others... | 61 | T19 | Mitsubishi | 62 | T21 | Mitsubishi - Subaru | 63 | T17 | Ford - Mazda | 64 | T8 | Chrysler - Renault | 65 | T18 | Suzuki | 66 | -- | Suzuki | 67 | T31 | Toyota | 69 | T22 | Yamaha Cycles | 70 | -- | Toyota EU | 71 | -- | Suzuki Cycles | 72 | -- | Kawasaki Cycles |
| Silca TRP ID              | Silca TRP  | Main Use                               |           |          |    |               |  |    |     |            |    |     |                     |    |     |              |    |    |                    |    |     |        |    |    |        |    |     |        |    |     |               |    |    |           |    |    |               |    |    |                 |
| 60                        | T7- T13 - T16  | Ford - Nissan- Kia, Hyundai, others... |           |          |    |               |  |    |     |            |    |     |                     |    |     |              |    |    |                    |    |     |        |    |    |        |    |     |        |    |     |               |    |    |           |    |    |               |    |    |                 |
| 61                        | T19  | Mitsubishi                             |           |          |    |               |  |    |     |            |    |     |                     |    |     |              |    |    |                    |    |     |        |    |    |        |    |     |        |    |     |               |    |    |           |    |    |               |    |    |                 |
| 62                        | T21  | Mitsubishi - Subaru                    |           |          |    |               |  |    |     |            |    |     |                     |    |     |              |    |    |                    |    |     |        |    |    |        |    |     |        |    |     |               |    |    |           |    |    |               |    |    |                 |
| 63                        | T17  | Ford - Mazda                           |           |          |    |               |  |    |     |            |    |     |                     |    |     |              |    |    |                    |    |     |        |    |    |        |    |     |        |    |     |               |    |    |           |    |    |               |    |    |                 |
| 64                        | T8   | Chrysler - Renault                     |           |          |    |               |  |    |     |            |    |     |                     |    |     |              |    |    |                    |    |     |        |    |    |        |    |     |        |    |     |               |    |    |           |    |    |               |    |    |                 |
| 65                        | T18  | Suzuki                                 |           |          |    |               |  |    |     |            |    |     |                     |    |     |              |    |    |                    |    |     |        |    |    |        |    |     |        |    |     |               |    |    |           |    |    |               |    |    |                 |
| 66                        | --   | Suzuki                                 |           |          |    |               |  |    |     |            |    |     |                     |    |     |              |    |    |                    |    |     |        |    |    |        |    |     |        |    |     |               |    |    |           |    |    |               |    |    |                 |
| 67                        | T31  | Toyota                                 |           |          |    |               |  |    |     |            |    |     |                     |    |     |              |    |    |                    |    |     |        |    |    |        |    |     |        |    |     |               |    |    |           |    |    |               |    |    |                 |
| 69                        | T22  | Yamaha Cycles                          |           |          |    |               |  |    |     |            |    |     |                     |    |     |              |    |    |                    |    |     |        |    |    |        |    |     |        |    |     |               |    |    |           |    |    |               |    |    |                 |
| 70                        | --   | Toyota EU                              |           |          |    |               |  |    |     |            |    |     |                     |    |     |              |    |    |                    |    |     |        |    |    |        |    |     |        |    |     |               |    |    |           |    |    |               |    |    |                 |
| 71                        | --   | Suzuki Cycles                          |           |          |    |               |  |    |     |            |    |     |                     |    |     |              |    |    |                    |    |     |        |    |    |        |    |     |        |    |     |               |    |    |           |    |    |               |    |    |                 |
| 72                        | --   | Kawasaki Cycles                        |           |          |    |               |  |    |     |            |    |     |                     |    |     |              |    |    |                    |    |     |        |    |    |        |    |     |        |    |     |               |    |    |           |    |    |               |    |    |                 |



### Fixed code Texas Transponder:

| Silca TRP ID | Silca TRP | Main Use                                       |
|--------------|-----------|--|
| 4C           | T3 - T4   | Ford, Toyota, Kia, Hyundai, Suzuki, others ... |

### Philips Crypto2 Transponders:

| Silca TRP ID | Silca TRP | Main Use  |
|--------------|-----------|---|
| 46           | T14       | Peugeot, Citroen, Kia, Hyundai, Honda, others ... |
| 46           | T32       | Chrysler – Renault Dacia                          |
| 46           | --        | Mitsubishi CDP                                    |
| 46           | --        | Mitsubishi Colt                                   |
| 46           | --        | GM USA Circle +                                   |

(\*\*\*) See the Silca vehicle guide and Silca Transponder Program for a list of vehicle models whose codes can be generated on a GTI transponder.

#### c) New Texas Crypto transponder ID

- ID (71) Texas Crypto used on Suzuki motor bikes
- ID (72) Texas Crypto used on Kawasaki motor bikes

#### d) New Texas Crypto 80 BITS transponder ID

- ID (6E-80) Texas Crypto 80 BITS (DST80)
- ID (6E-F4) Texas Crypto 80 BITS (DST40 Fast Auth)
- ID (6E-F8) Texas Crypto 80 BITS (DST80 Fast Auth)
- ID (6E-MA) Texas Crypto 80 BITS (DST+ Mutual Authentication)




To use these new functions with the following devices:

- RW4 + P-Box
- Fast Copy + P-Box
- RW4 PLUS
- Fast Copy PLUS


you need to update the on-board software of all the devices listed above (including P-Box). The "RW" software updates can also be downloaded from the internet through Silca Remote Service.






| Triax / QCODE family | Modified SSN  | Key-system | Brand |
|----------------------|---|------------|-------|
|                      | Corrected the measurement on first step of axis 2 and 3 |            |       |

|   |                     |                                      |              |
|---|---------------------|--------------------------------------|--------------|
| <br><b>Bug fixed</b> | 1409                | 5000 PS (6+4+5)                      | AGB          |
|   | 1440                | 5000 U-TECH PS (6+4+5)               | AGB          |
| <b>Unocode299/399 family</b>  | <b>New SSN/card</b> | <b>Key-system</b>                    | <b>Brand</b> |
|                      | 4433/3615           | Merkur 401 Indirect Code Head-> Tip  | RUKO         |
|   | 4434/3465           | Merkur 401 Indirect Code Tip -> Head | RUKO         |
| <b>UC199 machine</b>  | <b>New SSN/card</b> | <b>Key-system</b>                    | <b>Brand</b> |
|                      | 3749/3667           |                                      | HYUNDAI      |
|   | 3750/3667           |                                      | KIA          |
|   | 3946/3667           |                                      | KIA          |
|   | 3696/3667           |                                      | HYUNDAI/KIA  |




## September 2013 (for SKP Web subscribers) 2\_2013 - SILCA KEY PROGRAMS v. 19.4.1.x


| Triax / QCODE family  | Modified SSN  | Key-system        | Brand   |
|---|---|-------------------|---------|
| <br><b>Bug fixed</b> | Corrected a problem related to the cutting algorithm        |                   |         |
|   | 1264  | Mauer NW4 (4T-4W) | TRELOCK |
|   | Renamed depths according to manufacturer specifications     |                   |         |
|   | 799   | WKM3-WKM4 (6P)    | GERDA   |
|   | Added depth 0 to all axis                                   |                   |         |
|   | 1158  | 4000S Omega       | KESO    |
|   | Renamed the system according to manufacturer specifications |                   |         |
|   | 1444  | SPK (prof.161)    | BASI    |

| Triax / QCODE family  | New SSN  | Key-system   | Brand      |
|---|--|--------------|------------|
|  | 1458   | CX6a (6P)    | BASI       |
|   | 1459   | WS42         | BKS        |
|   | 1460   | OC4 (6P)     | OMEC       |
|   |  1461 | T250 (6+5P)  | TITAN      |
|   |  1461 | T250 (2T-5W) | TITAN      |
|   | 1463   | Prefer (6P)  | PREFER     |
|   | 1464   | DEC260       | DORMA-ISEO |
|   | 1465   | DEC261       | DORMA-ISEO |

| Unocode299/399 family and UC199 | New SSN/card | Key-system | Brand |
|---------------------------------|--------------|------------|-------|
|                                 | 4428/1401    | Dec 150    | DORMA |
|                                 | 4429/2668    | Dec 160    | DORMA |





|   |   |           |            |
|---|---|-----------|------------|
|  | 4432/3708   | E90       | ABUS       |
|   |  4431/3707 | Plura     | DOM        |
|   |  3925/2817 | Sigma     | DOM        |
|   | 4430/3706   | PX-PXP    | GEGE       |
|   | 4436/3719   | HDI+/VIP+ | VACHETTE   |
|   | 4435/3718   |           | PREFER     |
|   | 4437/2609   |           | EURO LOCKS |

| UC199 machine   | New function                            |
|---|---|
|  | Database version now available on-board |


July 2013 (for All SKP subscribers)


**2\_2013 - SILCA KEY PROGRAMS v. 19.4.x.x**


| Silca Key Programs UPGRADE 2/2013   |  |   |
|---|--|---|
|  | For any info regarding the 2/2013 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS. |  |

June 2013 (for SKP Web subscribers)


**1\_2013 - SILCA KEY PROGRAMS v. 19.3.7.x**

| Silca Key Programs  | New function   |
|---|--|
|  | <ul style="list-style-type: none"> <li>- In SSI is now possible to import a .DAT or XML KESO file with a maximum of 10000 rows</li> <li>- When updating via WEB, it is now possible to view the News document before downloading the Silca Key Programs</li> </ul> |


| Silca Transponder Program   | New function   |
|---|--|
|  | <ul style="list-style-type: none"> <li>- Update with 276 new automotive models</li> <li>- The STP database has been updated with all ILCO keys and all automotive transponder models available in <b>ILCO 2013 Automotive catalogue</b></li> </ul> |


| Triax / QCODE family  | Modified SSN   | Key-system      | Brand   |
|---|--|-----------------|---------|
| <br><b>Bug fixed</b> | Corrected a problem related to the cutting algorithm |                 |         |
|   | 1411   | Trelock (4T-4W) | TRELOCK |



| Triax / QCODE family  | New SSN             | Key-system  | Brand |
|---|---------------------|---|-------|
|  | 1417-1418-1419-1420 | BRAVUS series 1000, 2000, 3000, 4000  | ABUS  |
|   | 1427                | HONDA car models Brio e Amage   | HONDA |
|   | 1426                | SE ANS ( ANS-2 ANS-3 ANS-4 )  | GEGE  |
|   | 777                 | SE ( AP1000-AP2000-AP3000-AP4000-APN-CNS-2 CNS-3-HKS-2-pExtra-pExtra 3-pExtra (Swe) | GEGE  |



| Unocode299/399 family   | New SSN/card | Key-system  | Brand   |
|---|--------------|-------------|---------|
|  | 4418/3659    | EVEREST 29  | SCHLAGE |
|   | 2721/802     | Briton 7500 | SCHLAGE |


| UC199 machine   | New function   |
|---|--|
|  | - Two new adapters are available : for <b>FO21P (D708704ZB)</b> and for <b>SIMPLEX (D708040ZB)</b> |


| Viper machine   | New SSN | Key-system                  | Brand |
|---|---------|-----------------------------|-------|
|  | 2127    | HONDA models Brio and Amage | HONDA |

May 2013 (for SKP Web subscribers)


1\_2013 - **SILCA KEY PROGRAMS v. 19.3.6.x**


| Silca Key Programs  | New function   |
|---|--|
|  | New icon  allows for a direct connection to <a href="http://www.silca.biz">www.silca.biz</a> web site in order to obtain more info on the Silca Key Program . |



| Triax / QCODE family  | Modified SSN                                  | Key-system      | Brand   |
|---|---|-----------------|---------|
| <br><b>Bug fixed</b> | Corrected a problem related to the code list. |                 |         |
|   | 1304  | Kia (2T-8W)     | KIA     |
|   | Corrected the depth of cut.                   |                 |         |
|   | 1304  | Kia (2T-8W)     | KIA     |
|   | 1305  | Hyundai (2T-8W) | HYUNDAI |

| Triax / QCODE family  | New SSN | Key-system              | Brand      |
|---|---------|-------------------------|------------|
|  | 1412    | Subaru Forester (4T-5W) | TOKAJ RIKA |



|  |      |              |     |
|--|------|--------------|-----|
|  | 1414 | GMC (2T-10W) | HUF |
|--|------|--------------|-----|

| Unocode299/399 family   | New SSN | Key-system                              | Brand  |
|---|---------|---|--------|
|  | 4287    | (models BRZ,IMPREZA,TREZIA,FORESTER,XV) | SUBARU |
|   | 4417    | RH4/5 41/50mm                           | ABUS   |
|   | 4416    | Depth 0-1-2-3-4 (MIW13)                 | MIWA   |


| UC199 machine   | New function                         |
|---|--------------------------------------|
|  | New Swedish language on the machine. |


| Viper machine  | New SSN  | Key-system               | Brand      |
|--|--|--------------------------|------------|
|   | 2112   | Subaru Forester (4T-5W)) | TOKAJ RIKA |
|  | 2113   | GMC (2T-10W)             | HUF        |
|  | A new function has been added to the machine related to Card / SN search based on Edge / High security key ( snake type key ). |                          |            |


## March 2013 (for All SKP subscribers) **1\_2013 - SILCA KEY PROGRAMS v. 19.3.x.x**

| Silca Key Programs UPGRADE 1/2013   |  |   |
|---|--|---|
|  | For any info regarding the 1/2013 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS. |  |

## February 2013 (for SKP Web subscribers) **3\_2012 - SILCA KEY PROGRAMS v. 19.2.0.x**

| Unocode 299/399/EVO   | New SSN | Key-system       | Brand |
|---|---------|------------------|-------|
|  | 4383    | P600 Tip -> Head | ASSA  |

| Triax and QCODE   | Modified SSN   | Key-system     | Brand    |
|---|--|----------------|----------|
|  | Corrected a problem related to leaving axis 1 completely blank |                |          |
|   | 55   | Kalotten VS630 | WINKHAUS |
|   | 115  | Kalotten VS6   | WINKHAUS |
|   | 257  | Kalotten VS400 | WINKHAUS |

| Viper   |  |
|---|--|
| <br><b>Bug fixed</b> | Corrected a problem related to C clamp recognition |

## Silca KEY Programs



### Silca Transponder Program Upgrade



Software upgrade version 3.04.062 for RW devices ( RW4\*, RW4 PLUS, FASTCOPY\*, FASTCOPY PLUS )

From this version RW devices are able to make a copy of original keys for all vehicles that use Philips® Crypto2 transponders ID46 turning on the vehicle instrument panel just once (acquiring data by means of SNOOP).

This function is useful if data cannot be acquired when the vehicle instrument panel is turned on for the second time (the second LED on SNOOP does not illuminate).

The table below shows the models for which a second data acquisition session was not possible before (the second LED on SNOOP does not illuminate) and which can now be copied with this new method:

| Make     | Model      | Year from | Year to | SILCA REF |
|----------|------------|-----------|---------|-----------|
| CRHYSLER | PT CRUISER | 2006      | 2010    | CY24MH    |
| DODGE    | CARAVAN    | 2004      | 2007    | CY24MH    |
| HONDA    | ACCORD     | 2011      |         | HON60MH   |
| HONDA    | PILOT      | 2011      |         | HON60MH   |

(\* ) To use the new copying method please update your RW4 or FASTCOPY device plus the P-BOX device.

Consult the updated manuals for further information.




Starting with this version, code generation for the Temic® transponder (ID11) has been improved: with the old version invalid codes could be generated.



### Silca Software Interface

#### Silca Software interface has now 2 new functions

- Pressing the button “Select range” is possible to select a range of items to be sent to the machines
- The new column named “TX” shows the status of transmission to the machine



Unocode 299/399 family

New SSN

Key-system

Brand



# SKP PRO WEB Update



|  |      |                       |      |
|--|------|-----------------------|------|
|  | 4375 | CES PSM ( 5,6,7 pin ) | CES  |
|  | 4378 | Abus NW52             | ABUS |
|  | 4379 | Abus NW72             | ABUS |

**December 2012 (for All SKP subscribers) 3\_2012 - SILCA KEY PROGRAMS v. 19.1.x.x**  
**Silca Key Programs UPGRADE 3/2012**

## IMPORTANT



Silca Key programs is now **Windows® 8 (32 or 64 bit)** compliant.

To use the Silca Help note, it's required to install a Microsoft software patch available from <http://www.microsoft.com/en-us/download/details.aspx?id=35449> or ask your local

For any info regarding the 3/2012 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS



November 2012 (for SKP Web subscribers) 2\_2012 - **SILCA KEY PROGRAMS v. 18.8.3.x**

|  |   |  |   |
|--|---|--|---|
| <p><b>Silca KEY Programs</b></p>  | <p>SKP manages a new automatic compact key cutting machine for flat keys named <b>UC199</b>. Most of flat key cards can be cut by this machine with high precision.</p> |  |   |
| <p><b>Unocode 299/399 family</b></p>   | <p><b>New SSN</b></p>   | <p><b>Key-system</b></p>   | <p><b>Brand</b></p>   |
|                                   | <p>4354<br/>4355<br/>4356<br/>4357<br/>4358<br/>4359<br/>4360<br/>2171</p>  | <p>d12 SERIE 1200 (Prof. B21-01)<br/>d12 SERIE 1200 (Prof. B22-02)<br/>d12 SERIE 1200 (Prof. B23-03)<br/>d12 SERIE 1200 (Prof. B24-04)<br/>d12 SERIE 1200 (Prof. B25-05)<br/>d12 SERIE 1200 (Prof. B26-06)<br/>d12 SERIE 1200 (Prof. B27-07)<br/>PZ 88</p> | <p>ASSA<br/>ASSA<br/>ASSA<br/>ASSA<br/>ASSA<br/>ASSA<br/>ASSA<br/>BKS</p> |

|  |  |
|--|--|
| <p><b>Silca KEY Programs</b></p> <p style="text-align: center;"></p> | <p>-From SSI now is possible to create a indirect code-list selecting the desired SSI column. This function could be useful to locksmiths that manage XML KESO files.</p> <div style="text-align: center;"> </div> |
|--|--|

| <b>Triax and QCODE family</b> | <b>Modified SSN</b> | <b>Key-system</b>         | <b>Brand</b> |
|-------------------------------|---------------------|---------------------------|--------------|
|                               | 1323                | TEC RPS/RPE               | WINKHAUS     |
|                               | 1160                | T200                      | TITAN        |
|                               | 351                 | Mitsubishi HU56RP (2T-8W) | HUF          |
|                               | 486                 | Volvo HU56R (2T-8W)       | HUF          |
|                               | 936                 | K1 (6P)                   | SECUREMME    |
|                               | 802                 | K2 (5+5P)                 | SECUREMME    |

|  | <b>New SSN</b> | <b>Key-system</b>             | <b>Brand</b> |
|--|----------------|-------------------------------|--------------|
|  | 1356           | Lexus (2T-4W)                 | TOKAJ RICA   |
|  | 1357           | Ford (2T-7W)                  | HUF          |
|  | 1359           | Astral Tekno Special Profiles | CISA         |
|  | 1361           | Serial XP Special Profiles    | BRICARD      |
|  | 1358           | Tostem (4T-7W)                | TOSTEM       |
|  | 1363           | KX3-PMK                       | KAKEN        |
|  | 1364           | KX3-BH                        | KAKEN        |

| <b>Unocode 299/399 family</b> | <b>New SSN</b> | <b>Key-system</b> | <b>Brand</b> |
|-------------------------------|----------------|-------------------|--------------|
|                               | 4315           | PRO 300 – 30/35   | TOKOZ        |
|                               |                |                   |              |

| <b>Viper machine</b> | <b>Modified SSN</b> | <b>Key-system</b>         | <b>Brand</b> |
|----------------------|---------------------|---------------------------|--------------|
|                      | 351                 | Mitsubishi HU56RP (2T-8W) | HUF          |
|                      | 486                 | Volvo HU56R (2T-8W)       | HUF          |

|  | <b>New SSN</b> | <b>Key-system</b>     | <b>Brand</b> |
|--|----------------|-----------------------|--------------|
|  | 2042           | Lexus (2T-4W)         | LEXUS        |
|  | 2043           | Huf-Mahindra (2T-10W) | MAHINDRA     |
|  | 2044           | Man (2T-8W)           | MAN          |
|  | 2045           | Ford (2T-7W)          | FORD         |





# SKP PRO WEB Update



July 2012 (for All SKP subscribers)

2\_2012 - **SILCA KEY PROGRAMS v. 18.7.x.x**

**Silca Key Programs UPGRADE 2/2012**

## IMPORTANT

Due to the need to upgrade Silca Key Programs, from the SKP 2/2012 Update, Windows 2000 Operating System will no longer be supported.




On request, Silca will provide the relative DVD free to web subscribers who have to install the update on a new PC

For any info regarding the 2/2012 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS



May 2012 (for SKP Web subscribers)

1\_2012 - **SILCA KEY PROGRAMS v. 18.5.0.x**

|  |  |   |                          |
|--|--|---|--------------------------|
|  <p><b>Silca Transponder Program Upgrade</b></p>  | <p><b>Identification of TEXAS/CRYPTO keys with Mutual Authentication (ID=6E)</b></p> <p>From this version ( 3.02.061 ) RW devices can detect keys using Texas Crypto Transponder with Mutual Authentication ( 6E ) that cannot be duplicated.</p> <p>Texas Crypto 6E is used on the most recent car models of :</p> <ul style="list-style-type: none"> <li>- FORD ( with Texas 80 bit transponder )</li> <li>- TOYOTA ( with "G system" transponder )</li> <li>- KIA, HYUNDAI, SUBARU ( most of them with Texas 80 bit transponder )</li> </ul> <p>The Silca Transponder Program has been updated with 145 applications including the new MH key and other 25 new car models.</p> <p>68 MH key references are now available.</p> <p>Remember to upgrade the internal SW of RW4, RW4 PLUS, FASTCOPY, FASTCOPY PLUS devices.</p> |   |                          |
|  | <p><b>Unocode 299/399 family</b></p>    | <p><b>New SSN</b></p>                             | <p><b>Key-system</b></p> |
|  | 4286   | Cylinders   | ANKER                    |
|  | 4287   | For SUBARU Models: Trezia 2011, XV 2012, BRZ 2012 | SUBARU                   |

March 2012 (for All SKP subscribers)

1\_2012 - **SILCA KEY PROGRAMS v. 18.4.x.x**

**Silca Key Programs UPGRADE 1/2012**

For any info regarding the 1/2012 SKP Upgrade, please, read the NEWS document in the SILCA KEY PROGRAMS

